

ERRATUM to "NEUTRON DOSIMETRY AND DAMAGE CALCULATIONS FOR THE HFIR-MFE-200J-1 IRRADIATION," in Fusion Materials Semiannual Progress Report for Period Ending December 31, 1997, DOE/ER-0313/23, pp. 329–332.

Table 2 of this report contains an error. The thermal neutron fluence should be $0.35 \times 10^{22} \text{ n/cm}^2$. The error has been corrected, and a revised version of the report is available on-line in DOE/ER-0313/23. Anyone who downloaded and/or referred the original report is encouraged to obtain the corrected copy.