Oak Ridge Reservation
Quality Assurance Report
for Meteorological Towers
For Towers A, B, C, K, L, M, W, Y

Kevin R. Birdwell Computational Science and Engineering Division Oak Ridge National Laboratory

January 2008

### **Tower ID Summary:**

Name	Alternate Names	ORR Site	Elevation (m)	Easting, Northing (m)	Measuring Hts
Tower A	MT4, 7571	ORNL	263	743179,3978105	10,30
Tower B	MT3, 6555, 07	ORNL	256	743398,3979683	10,30
Tower C	MT2, 1057, 03	ORNL	261	741423,3978768	10,30,100
Tower K	MT1, 1208	ETTP	253	735675,3979503	10,60
Tower L	MT7, 1209	ETTP	233	735110,3978654	10,30
Tower M	1208A, 208A	ETTP	237	735720,3976860	10
Tower W	MT6, Y12W, West	Y12	326	748890,3986700	10,60
Tower Y	2006Tower	Y12	290	747926.3985859	2, 15, 33

Tuesday, January 1, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Arctic front enters area early AM (1-2am); snow showers began around 1600 hrs.

Wednesday, January 2, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, January 3, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, January 4, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, January 5, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range		ı Recovered 60-min	Sensors Affected	Comments
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	1530	99.0	100.0	All	Y12 network timing error
Tower Y	ERR	1530	99.0	100.0	All	Y12 network timing error

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, January 6, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, January 7, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, January 8, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, January 9, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, January 10, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thunderstorms 6:30-8am and from 7-9 pm; Warm front passage around 5 pm

Friday, January 11, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Cold front passage between 1 and 4 am.

Saturday, January 12, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, January 13, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	ERR	1126-1127	100.0 100.0	All	Power failure caused temporary loss of data
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, January 14, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, January 15, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered	Sensors Affected	Comments
		15-min 60-min		
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, January 16, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

### SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Reco 15-min 60-i	33	Comments
Tower A	OK		100.0 100	.0	
Tower B	OK		100.0 100	.0	
Tower C	ERR	0345-0851	75.0 75	.0 All	Data logger freeze-up; system rebooted at 0851hrs and deemed OK (possible cause – power fluctuation?)
Tower K	OK		100.0 100	.0	-
Tower L	OK		100.0 100	.0	
Tower M	OK		100.0 100	.0	
Tower W	OK		100.0 100	.0	
Tower Y	OK		100.0 100	.0	

#### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

Dasmet 0345-0851 75.0 Communication line failure?

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sleet began around 10-11 pm.

Thursday, January 17, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sleet occurred from about 12 to 4 am

Friday, January 18, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, January 19, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Arctic frontal passage around 1 to 2 pm

Sunday, January 20, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range		n Recovered 60-min	Sensors Affected	Comments
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	1115, 2015	98.0	100.0	All	Y12 network timing error
Tower Y	ERR	1115, 2015	98.0	100.0	All	Y12 network timing error

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, January 21, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered	Sensors Affected	Comments
		15-min 60-min		
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0	All	Quarterly calibrations performed by Shaw En.v
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, January 22, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

#### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Freezing rain from 6:30 am thru 8am

Fatality reported due to black ice at 7:09 am ½ mile east of ORNL East Portal

Wednesday, January 23, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	a Recovered	Sensors Affected
		ū	15-min	60-min	
Tower A	OK		100.0	100.0	
Tower B	OK		100.0	100.0	
Tower C	ERR	1703-1725	98.0	96.0	Temp10
	ERR	1642-1700	98.0	96.0	Temp30
	ERR	1611-1627	98.0	96.0	Temp100
	ERR	1703-1725	98.0	96.0	WindDir10
	ERR	1642-1700	98.0	96.0	WindDir30
	ERR	1612-1626	98.0	96.0	WindDir100
	ERR	1708-1725	98.0	96.0	WindSpd10
	ERR	1643-1707	98.0	96.0	WindSpd30
	ERR	1612-1628	98.0	96.0	WindSpd100
Tower K	OK		100.0	100.0	
Tower L	OK		100.0	100.0	
Tower M	OK		100.0	100.0	
Tower W	OK		100.0	100.0	
Tower Y	OK		100.0	100.0	

#### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

None

#### Comments

Quarterly calibrations performed by Shaw Env. Quarterly calibrations performed by Shaw Env.

Thursday, January 24, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	ERR	0355-0356, 2022-2023	100.0 100.0	All	Power failures affecting 4 minutes of data
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Arctic Front crossed area around 8-9 am EST

Friday, January 25, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, January 26, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, January 27, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, January 28, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
T .	OTZ		15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	ERR	0929-0930	100.0 100.0	All	Power failure affecting 2 minutes of data
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, January 29, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

#### SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	2318-2359	97.0 96.0	All	Missing data (power failure caused by high winds)
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

#### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wind gust of 63 mph occurred between 11 pm and Midnight at 10 meter level on Tower C; wind gust was 111 mph at 100 meter level.

Wednesday, January 30, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

### SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	ERR	0000-0045	97.0	96.0	All	Missing data (power failure caused by high winds)
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0915	99.0	100.0	All	Y12 network timing error
Tower Y	ERR	0915	99.0	100.0	All	Y12 network timing error

#### NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wind gust of 66 mph occurred between Midnight and 2 am at 10 meter level on Tower C