Oak Ridge Reservation
Quality Assurance Report
for Meteorological Towers
For Towers A, B, C, K, L, M, W, Y

Kevin R. Birdwell Computational Science and Engineering Division Oak Ridge National Laboratory

May 2008

Tower ID Summary:

Name	Alternate Names	ORR Site	Elevation (m)	Easting, Northing (m)	Measuring Hts
Tower A	MT4,7571	ORNL	263	743179,3978105	10,30
Tower B	MT3, 6555, 07	ORNL	256	743398,3979683	10,30
Tower C	MT2, 1057, 03	ORNL	261	741423,3978768	10,30,100
Tower K	MT1, 1208	ETTP	253	735675,3979503	10,60
Tower L	MT7, 1209	ETTP	233	735110,3978654	10,30
Tower M	MT10, 208A	ETTP	237	735720,3976860	10
Tower W	MT6, Y12W, West	Y12	326	748890,3986700	10,60
Tower Y	MT9, PSS Tower	Y12	290	747926.3985859	15, 33

Thursday, May 1, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0215, 1200	98.0	100.0	All	Missing data (Y12/ORNL network timing error)
Tower Y	ERR	0215, 1200	98.0	100.0	All	Missing data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, May 2, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	1730, 1900-1915	97.0	100.0	All	Missing data (unknown error)
Tower Y	OK		100.0	100.0		-

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, May 3, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

1800-1900 pm Mountain wave showers active in Northern Anderson County / Union County (Norris – Andersonville area).

Sunday, May 4, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0345, 1345	98.0	100.0	All	Missing data (Y12/ORNL network timing error)
Tower Y	ERR	1345	99.0	100.0	All	Missing data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, May 5, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	1530, 1645	98.0	100.0	All	Missing data (Y12/ORNL network timing error)
Tower Y	ERR	1530, 1915	98.0	100.0	All	Missing data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, May 6, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, May 7, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Re	ecovered	Sensors Affected	Comments
			15-min 60	0-min		
Tower A	OK		100.0 10	0.00		
Tower B	OK		100.0 10	0.00		
Tower C	OK		100.0 10	0.00		
Tower K	OK		100.0 10	0.00		
Tower L	OK		100.0 10	0.00		
Tower M	OK		100.0 10	0.00		
Tower W	ERR	0345	99.0 10	0.00	All	Missing data (Y12/ORNL network timing error)
Tower Y	OK		100.0 10	0.00		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, May 8, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered	Sensors Affected	Comments
		15-min 60-min		
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, May 9, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	0600	99.0 100.0	All	Missing data (modem/communication error)
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thunderstorms in area around 8 pm EDT.

Saturday, May 10, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	a Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0415, 0645	99.0	100.0	All	Missing data (Y12/ORNL network timing error)
Tower Y	ERR	0415	98.0	100.0	All	Missing data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, May 11, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0000-0015, 2145	97.0	100.0	All	Missing data (Y12/ORNL network timing error)
Tower Y	ERR	0000-0015, 2145	97.0	100.0	All	Missing data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thundershowers in area around 4-6 am.

Monday, May 12, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK	1745-1845	96.0	96.0	None	Quarterly calibrations performed by Shaw Environmental
Tower B	OK		100.0	100.0		
Tower C	ERR	1508-1726	90.0	90.0	Some, Intermittent	Missing data (Quarterly calibrations performed by Shaw Environmental)
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	1115-1445	86.0	84.0	All	Missing data (no data received from Y12)
Tower Y	ERR	1115-1445	86.0	84.0	All	Missing data (no data received from Y12)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, May 13, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	,	Recovered 60-min	Sensors Affected
Tower A	OK		13-min 100.0	100.0	
Tower B	OK		100.0	100.0	
Tower C	OK		100.0	100.0	
Tower K	OK		100.0	100.0	
Tower L	OK		100.0	100.0	
Tower M	OK		100.0	100.0	
Tower W	ERR	1000, 1400, 1745	97.0	100.0	All
Tower Y	ERR	1000, 1400, 1745	97.0	100.0	All

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

None

Comments

Quarterly calibrations performed by Shaw Environmental 0800-1100 hrs Quarterly calibrations performed by Shaw Environmental 1400-1600 hrs

Missing data (Programming on Dasmet; Y12-ORNL network error) Missing data (Programming on Dasmet; Y12-ORNL network error)

Wednesday, May 14, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	ERR	2045	99.0 100.0		Missing 15-min data (communication error)
Tower M	OK		100.0 100.0		-
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, May 15, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Rec	covered S	ensors Affected	Comments
			15-min 60)-min		
Tower A	OK		100.0 10	0.00		
Tower B	OK		100.0 10	0.00		
Tower C	OK		100.0 10	0.00		
Tower K	OK		100.0 10	0.00		
Tower L	OK		100.0 10	0.00		
Tower M	OK		100.0 10	0.00		
Tower W	ERR	0830	99.0 10	00.0 A	.11	Missing 15-min data (Y12/ORNL network timing error)
Tower Y	ERR	0830, 0945	98.0 10	00.0 A	.11	Missing 15-min data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered None

Cause/Repair

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, May 16, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recover	red Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	1700	99.0 100.0	All	Missing 15-min data (Y12/ORNL network timing error)
Tower Y	ERR	1700	99.0 100.0	All	Missing 15-min data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range None

%Data Recovered

Cause/Repair

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, May 17, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	1215	99.0 100.0	All	Missing 15-min data (communication error?)
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	2245	99.0 100.0	All	Missing 15-min data (Y12/ORNL network timing error)
Tower Y	ERR	2245	99.0 100.0	All	Missing 15-min data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, May 18, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range		Recovered 60-min	Sensors Affected	Comments
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	OK		100.0	100.0		
Tower Y	OK		100.0	100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thundershowers associated with cold front passage around 1800 hrs

Monday, May 19, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, May 20, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	0830	99.0 100.0	All	Missing 15-min data (communication error?)
Tower L	ERR	0900	99.0 100.0	All	Missing 15-min data (communication error?)
Tower M	OK		100.0 100.0		
Tower W	ERR	0830	99.0 100.0	All	Missing 15-min data (Y12/ORNL network timing error)
Tower Y	ERR	0830	99.0 100.0	All	Missing 15-min data (Y12/ORNL network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, May 21, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A Tower B Tower C Tower K Tower L Tower M Tower W Tower Y	ERR OK OK OK OK OK OK	1545	99.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0	All	Missing 15-min data (communication error?)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, May 22, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	ERR	1445, 2115	98.0	100.0	All	Missing 15-min data (reprogramming, modem error)
Tower B	ERR	1430-1445	98.0	100.0	All	Missing 15-min data (reprogramming, modem error)
Tower C	OK		100.0	100.0		
Tower K	ERR	1445, 2145, 2215-2230	95.0	100.0	All	Missing 15-min data (reprogramming, modem error)
		2345				
Tower L	ERR	1445	99.0	100.0	All	Missing 15-min data (reprogramming)
Tower M	ERR	1445, 1645-1900	88.0	88.0	All	Missing data (reprogramming, power failure?)
Tower W	ERR	1430-1445	98.0	100.0	All	Missing 15-min data (reprogramming)
Tower Y	ERR	0000, 0715, 1430-1445	96.0	100.0	All	Missing 15-min data (reprogramming, network error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, May 23, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0	All	
Tower B	OK		100.0	100.0	All	
Tower C	OK		100.0	100.0		
Tower K	ERR	0030-0045, 0115, 0200	88.0	100.0	All	Missing 15-min data (modem errors?)
		0300, 0345, 0415-0430				
		0700, 0915, 1130				
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	OK		100.0	100.0		
Tower Y	OK		100.0	100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, May 24, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data 1	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	ERR	2100	100.0	100.0	All	Missing 15-min data (modem errors?)
Tower B	OK		100.0	100.0	All	
Tower C	OK		100.0	100.0		
Tower K	ERR	0100-0145, 0900-0945	84.0	84.0	All	Missing 15-min data (modem errors?)
		1100-1145, 1400-1445				
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0015, 0745-0800	97.0	100.0	All	Missing 15-min data (Y12/ORNL network timing
						error)
Tower Y	ERR	0745-0800	98.0	100.0	All	Missing 15-min data (Y12/ORNL network timing
						error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, May 25, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	a Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0	All	
Tower B	OK		100.0	100.0	All	
Tower C	OK		100.0	100.0		
Tower K	ERR	1345, 1530, 1700, 1745	85.0	88.0	All	Missing 15-min data (modem errors?)
		1900, 1945-2015				-
		2045-2100, 2130, 2300				
		2330-2345				
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	OK		100.0	100.0		
Tower Y	ERR	0000-0015	98.0	100.0	All	Missing 15-min data (Y12/ORNL network timing
						error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, May 26, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	0000, 1930-2315	83.0 84.0	All	Missing 15-min data (modem error 0000, Lightning-related power failure)
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thunderstorms around 1800-2000 hrs; lightning affected Tower K data stream around 1920 hrs.

Tuesday, May 27, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recover	33	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	1600	99.0 100.0	All	Missing 15-min data (modem error)
Tower L	OK		100.0 100.0		-
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Terrain-induced small "air mass" showers noted during late morning on nearby Cumberland Plateau to immediate west of ORNL

Wednesday, May 28, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range		Recovered 60-min	Sensors Affected	Comments
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	ERR	0945-1015. 1100, 1130 1245, 1330-1345 1700-1715, 1845	89.0	100.0	All	Missing 15-min data (modem/software error)
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	OK		100.0	100.0		
Tower Y	OK		100.0	100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Terrain-induced shower stationary around Oliver Springs late afternoon.

Thursday, May 29, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	0015	99.0 100.0	All	Missing 15-min data (modem/software error)
Tower L	ERR	1430-1530	95.0 96.0	All	Missing data (power failure)
Tower M	ERR	1430-2345	60.0 60.0	All	Missing data (power failure caused modem error)
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, May 30, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	ERR	0000-2345	0.0	0.0	All	Missing data (power failure caused communication
						line error)
Tower W	OK		100.0	100.0		
Tower Y	OK		100.0	100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, May 31, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	ERR	0600, 0630, 0730-0800	92.0	96.0	All	Missing 15-min data (modem/software error)
		1000, 1145, 1500, 1645				
Tower L	OK		100.0	100.0		
Tower M	ERR	0000-2345	0.0	0.0	All	Missing data (power failure caused communication
						line error)
Tower W	ERR	2030	99.0	100.0	All	Missing 15-min data (Y12/ORNL network timing
						error)
Tower Y	ERR	2030	99.0	100.0	All	Missing 15-min data (Y12/ORNL network timing
						error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Partially mountain-related showers over North Anderson County between midnight and 2 am.