Oak Ridge Reservation
Quality Assurance Report
for Meteorological Towers
For Towers A, B, C, K, L, M, W, Y

Kevin R. Birdwell Computational Science and Engineering Division Oak Ridge National Laboratory

August 2008

Tower ID Summary:

Name	Alternate Names	ORR Site	Elevation (m)	Easting, Northing (m)	Measuring Hts
Tower A	MT4, 7571	ORNL	263	743179,3978105	10,30
Tower B	MT3, 6555, 07	ORNL	256	743398,3979683	10,30
Tower C	MT2, 1057, 03	ORNL	261	741423,3978768	10,30,100
Tower K	MT1, 1208	ETTP	253	735675,3979503	10,60
Tower L	MT7, 1209	ETTP	233	735110,3978654	10,30
Tower M	MT10, 208A	ETTP	237	735720,3976860	10
Tower W	MT6, Y12W, West	Y12	326	748890,3986700	10,60
Tower Y	MT9, PSS Tower	Y12	290	747926.3985859	15, 33

Friday, August 1, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovere	d Sensors Affected	Comments
			15-min 60-min		
Tower A	ERR	0215	99.0 100.0	All	Missing 15-min data (related to database error above)
Tower B	ERR	0215	99.0 100.0	All	Missing 15-min data (related to database error above)
Tower C	ERR	0215-0400	92.0 92.0	All	Missing data (communication line failure and
					database collection error)
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	0215	99.0 100.0	All	Missing 15-min data (related to database error above)
Tower Y	ERR	0215	99.0 100.0	All	Missing 15-min data (related to database error above)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

Tower C 0215-1030 92.0% Tower C lease line communication failure; data access restored 1030 hrs.

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, August 2, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Status	Time Range	% Data Recovered	Sensors Affected	Comments
		15-min 60-min		
OK		100.0 100.0		
ERR	0715-1000	88.0 88.0	All	Missing 15-min data (ORNL planned power failure)
OK		100.0 100.0		
OK		100.0 100.0		
OK		100.0 100.0		
OK		100.0 100.0		
ERR	2245, 2330-2345	970. 100.0	All	Missing 15-min data (network timing error)
ERR	2245, 2330-2345	970. 100.0	All	Missing 15-min data (network timing error)
	OK ERR OK OK OK OK ERR	OK ERR 0715-1000 OK OK OK OK ERR 2245, 2330-2345	OK 100.0 100.0 ERR 0715-1000 88.0 88.0 OK 100.0 100.0 ERR 2245, 2330-2345 970. 100.0	OK 100.0 100.0 ERR 0715-1000 88.0 88.0 All OK 100.0 100.0 ERR 2245, 2330-2345 970. 100.0 All

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, August 3, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered	Sensors Affected	Comments
		15-min 60-min		
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, August 4, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data F	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	ERR	0000	99.0	100.0	All	Missing 15-min data (modem/ communication line
						error)
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	2345	99.0	100.0	All	Missing 15-min data (network timing error)
Tower Y	ERR	2345	99.0	100.0	All	Missing 15-min data (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, August 5, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0815, 1045	98.0	100.0	All	Missing 15-min data (network timing error)
Tower Y	ERR	0815, 1045	98.0	100.0	All	Missing 15-min data (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, August 6, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	1330	99.0 100.0	All	Missing 15-min data (communication line/modem
Tower L	OK		100.0 100.0		-
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Apparent outflow boundary from decaying MCS system brushed northern portion of Oak Ridge area. Lightning was in around 0400-0500 hrs.

Thursday, August 7, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	ERR	2137-2345	89.0 88.0	All	Communication line failure (modem failure?)
Tower K	ERR	0945	99.0 100.0	All	Missing 15-min data (communication line/modem
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems	Time Range	%Data Recovered	Cause/Repai
Edas1, Dasmet	1800-2359	87.5	Communicat

Communication failure with Tower C (suspected modem failure) delayed or eliminated collection of data after 2100 hrs. Problems with Tower C communication caused large delays in collection of Tower A and B data which affected real time use of meteorological data from those sites.

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Weak/moderate small MCS crossed area around 0200-0300 hrs; terrain-related rejuvenation appears to have intensified precipitation over ORNL/ETTP (0.40-0.50 inches vs. 0.10 inches elsewhere). Lightning was observed during the event.

Friday, August 8, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

Edas 1, Dasmet 2130-2146 100.0 Communication failure with Tower C (suspected modem failure) delayed collection of data

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, August 9, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	0945	99.0 100.0	All	Missing 15-min data (modem communication error)
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

Edas1, Dasmet 1615-2345 100.0 Communication failure with Tower C (suspected modem or phone line failure)

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, August 10, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data .	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0315, 0345	98.0	100.0	All	Missing 15-min data (network timing error)
Tower Y	ERR	0315, 0345	98.0	100.0	All	Missing 15-min data (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

Edas 1, Dasmet 0000-2345 100.0 Communication failure with Tower C (suspected modem or phone line failure)

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, August 11, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	ERR	1315-2345	54.0	54.0	WD10, SIG10	Missing data (tower transferred to E-Das;
	ERR	1315-1400	96.0	96.0	Other	At 1315 hrs; wind direction programmed
TD 111	EDD	0215 0515	01.0	100.0	4.11	incorrectly)
Tower W	ERR	0315-0515	91.0	100.0	All	Missing data (unknown cause)
Tower Y	ERR	0515	99.0	100.0	All	Missing 15-min data (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

Edas 1, Dasmet 0000-0945 100.0 Communication failure with Tower C (suspected modem or phone line failure)

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Tower M transferred to E-Das data collection system.

Weather Notes

Tuesday, August 12, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data R	ecovered	Sensors Affected	Comments
			15-min 6	60-min		
Tower A	ERR	0715-2345	28.0	28.0	All	Missing data (Tower A power failure)
Tower B	OK		100.0 1	0.001		
Tower C	OK		100.0 1	0.001		
Tower K	OK		100.0 1	0.00		
Tower L	OK		100.0 1	0.00		
Tower M	ERR	0000-2345	0.0	0.0	WD10, SIG10	Values in error (programming error)
	OK		100.0	100.0	Other	
Tower W	OK		100.0 1	0.00		
Tower Y	OK		100.0 1	0.00		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, August 13, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	ERR	0000-2345	0.0 0.0	All	Missing data (Tower A power failure)
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	ERR	0000-2345	0.0 0.0	WD10, SIG10	Values in error (programming error)
	OK		100.0 100.0	Other	
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, August 14, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Re	ecovered	Sensors Affected	Comments
			15-min 6	0-min		
Tower A	ERR	0000-1645	28.0	28.0	All	Missing data (Tower A power failure; data restored via generator at 1700 hrs)
Tower B	OK		100.0 1	0.00		
Tower C	OK		100.0 1	0.00		
Tower K	ERR	2300	99.0 1	0.00	All	Missing 15-min data (modem communication error)
Tower L	OK		100.0 1	0.00		
Tower M	ERR	0000-1245	0.0	0.0	WD10, SIG10	Values in error (programming error; corrected at 1245 hrs)
	OK		100.0 1	0.00	Other	
Tower W	OK		100.0 1	0.00		
Tower Y	OK		100.0 1	0.00		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

None

Friday, August 15, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
Tower A	OK		15-min 60-min 100.0 100.0		Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	ERR	0900-0945	96.0 96.0	All	Data unavailable from 0900-0945 during logger reprogramming
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, August 16, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range			Recovered	Sensors Affected
Tower A	ERR	0500, 2100	15-min 98.0	60-min 100.0	
Tower B	OK		100.0	100.0	
Tower C	OK OK		100.0	100.0	
Tower K	OK		100.0	100.0	
Tower L	OK		100.0	100.0	
Tower M	OK		100.0	100.0	
Tower W	OK		100.0	100.0	
Tower Y	OK		100.0	100.0	

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

None

Comments

Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.

Sunday, August 17, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
Tower A	ERR	0600, 1700	15-min 60-min 98.0 100.0		Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	2315	99.0 100.0	All	15-min data missing (network timing error)
Tower Y	ERR	2315	99.0 100.0	All	15-min data missing (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, August 18, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
Tower A	ERR	0600	15-min 60-min 99.0 100.0	All	Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	1115, 1900	99.0 100.0	All	15-min data missing (network timing error)
Tower Y	ERR	1115, 1900	99.0 100.0	All	15-min data missing (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Date
None

%Data Recovered

Cause/Repair

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, August 19, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	ERR	0530, 1345	98.0 100.0	All	Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	1445-1545	950 96.0	All	Missing data (Quarterly calibrations performed by Shaw)
Tower Y	OK		100.0 100.0	All	,

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, August 20, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	1845	99.0 100.0	All	Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	1030	99.0 100.0	All	Missing 15-min data (communication line error)
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	1515	99.0 100.0	All	Missing 15-min data (network timing error)
Tower Y	OK		100.0 100.0	All	

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered None

Cause/Repair

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, August 21, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range		Recovered 60-min	Sensors Affected
Tower A	ERR	1600	99.0	100.0	All
Tower B	OK		100.0	100.0	
Tower C	OK		100.0	100.0	
Tower K	OK		100.0	100.0	
Tower L	OK		100.0	100.0	
Tower M	OK		100.0	100.0	
Tower W	OK		100.0	100.0	All
Tower Y	OK		100.0	100.0	All

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

None

Comments

Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.

Friday, August 22, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range		Recovered 60-min	Sensors Affected
Tower A	ERR	0630	99.0	100.0	All
Tower B	OK		100.0	100.0	
Tower C	OK		100.0	100.0	
Tower K	OK		100.0	100.0	
Tower L	OK		100.0	100.0	
Tower M	OK		100.0	100.0	
Tower W	OK		100.0	100.0	All
Tower Y	OK		100.0	100.0	All

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

None

Comments

Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.

Saturday, August 23, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	0745	99.0 100.0	All	Tower A on generator-power; intermittent power outages not significantly affecting 15-min or 60-min data.
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	0815-1030	89.0 89.0	All	Missing data (network connectivity error?)
Tower Y	ERR	0815-1030	89.0 89.0	All	Missing data (network connectivity error?)

Cause/Repair

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Dasmet 0815-1030

100% ORNL, ETTP; 89.0% Y12 Network connectivity error?

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, August 24, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
Tower A	ERR	0800	15-min 60-min 99.0 100.0	All	Tower A on generator-power; intermittent power outages not significantly affecting 15-min or
Tower B	OK		100.0 100.0		60-min data.
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range
Dasmet 0815-1030

%Data Recovered

100% ORNL, ETTP; 89.0% Y12

Cause/Repair

Network connectivity error?

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, August 25, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Red	covered	Sensors Affected	Comments
			15-min 60)-min		
Tower A	ERR	1530-1700	92.0 9	02.0	All	Quarterly calibrations performed by Shaw Environmental.
Tower B	OK		100.0 10	0.00		
Tower C	OK		100.0 10	0.00		
Tower K	OK		100.0 10	0.00		
Tower L	OK		100.0 10	0.00		Quarterly calibrations performed by Shaw Environmental.
Tower M	OK		100.0 10	0.00		
Tower W	ERR	0430	99.0 10	0.00	All	Missing data (network connectivity error?)
Tower Y	ERR	0430	99.0 10	0.00	All	Missing data (network connectivity error?)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered None

Cause/Repair

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, August 26, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recover	red Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	ERR	0130	99.0 100.0	All	Communication error
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered

Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, August 27, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	ERR	0700-0830	92.0	92.0	All	Tower A on generator-power; generator failure caused loss of data.
Tower B	ERR	1345-1445	94.0	92.0	All	Quarterly calibrations performed by Shaw Environmental.
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	2315	99.0	100.0	All	Missing 15-min data (network timing error)
Tower Y	ERR	2315	99.0	100.0	All	Missing 15-min data (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered None

Cause/Repair

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, August 28, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recov	ered Sensors Affected	Comments
			15-min 60-m	in	
Tower A	OK		100.0 100.0	1	
Tower B	OK		100.0 100.0		
Tower C	ERR	1115-1600	79.0 80.0	Intermittent	Sensors intermittently in error; Quarterly
					calibrations performed by Shaw Environmental
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0	1	
Tower W	ERR	2330	99.0 100.0	All	Missing 15-min data (network timing error)
Tower Y	ERR	2330	99.0 100.0	All	Missing 15-min data (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered None

Cause/Repair

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, August 29, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data R	Recovered	Sensors Affected	Comments
			15-min (50-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	ERR	0900-1045	92.0	92.0	Intermittent	Quarterly calibrations performed by Shaw
						Environmental; some readings may be in
						error.
Tower L	OK		100.0	100.0		
Tower M	OK			100.0		
Tower W	OK		100.0	100.0		
Tower Y	OK		100.0	100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, August 30, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered	Sensors Affected	Comments
		15-min 60-min		
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered None

Cause/Repair

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, August 31, 2008

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	2115	99.0	100.0	All	Missing 15-min data (network timing error)
Tower Y	ERR	2115	99.0	100.0	All	Missing 15-min data (network timing error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered

Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes