

MARTIN MARIETTA ENERGY SYSTEMS LIBRARIES



3 4456 0424047 1

ORNL/TM-11838

ornl

OAK RIDGE NATIONAL LABORATORY

MARTIN MARIETTA

In Situ Grouting of Low-Level Burial Trenches with a Cement-Based Grout at Oak Ridge National Laboratory

C. W. Francis
R. D. Spence
T. Tamura
B. P. Spalding

Environmental Sciences Division
Publication No. 3872

OAK RIDGE NATIONAL LABORATORY
CENTRAL RESEARCH LIBRARY
CIRCULATION SECTION
4500N ROOM 175

LIBRARY LOAN COPY

DO NOT TRANSFER TO ANOTHER PERSON

If you wish someone else to see this
report, send in name with report and
the library will arrange a loan.

UCR-7689 (3-87)



MANAGED BY
MARTIN MARIETTA ENERGY SYSTEMS, INC.
FOR THE UNITED STATES
DEPARTMENT OF ENERGY

This report has been reproduced directly from the best available copy.

Available to DOE and DCE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (615) 576-8401, FTS 626 8401.

Available to the public from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Environmental Sciences Division

**In Situ Grouting of Low-Level Burial Trenches
with a Cement-Based Grout
at Oak Ridge National Laboratory**

C. W. Francis
R. D. Spence^a
T. Tamura^b
B. P. Spalding

Environmental Sciences Division Publication No. 3872

^aChemical Technology Division

^bHazwrap Program

Date Published—January 1993

Prepared for the
Office of Technology Development
(EW 40 10 50 0; 3TAG000)

Prepared by the
OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831-6285
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U.S. Department of Energy
under contract DE-ACO5-84OR21400

MARTIN MARIETTA ENERGY SYSTEMS LIBRARIES



3 4456 0424047 1

CONTENTS

LIST OF FIGURES	v
LIST OF TABLES	vii
ABSTRACT	ix
1. INTRODUCTION	1
2. METHODS AND MATERIALS	5
2.1 SITE DESCRIPTION	5
2.2 SOIL-PENETRATION TESTS	5
2.3 INSTALLATION OF INJECTION WELLS	5
2.4 HYDRAULIC CONDUCTIVITY MEASUREMENTS	8
2.4.1 PregROUTed Trenches	8
2.4.2 PostgROUTed Trenches	9
2.5 VOID-VOLUME MEASUREMENTS	9
2.5.1 Trench Pressurization--Theory	11
2.5.2 Trench Pressurization--Applied	14
2.5.3 Water Pump-In Tests	15
2.6 GROUNDWATER MONITORING	20
2.7 GROUT FORMULATION AND TESTING	20
2.7.1 Phase Separation Tests	21
2.7.2 Compressive Strength Tests	21
2.7.3 Penetration Resistance	22
2.7.4 Apparent Viscosity	22
2.7.5 Gel Strength	22
2.7.6 Consistency	22
2.8 FIELD GROUT MIXING AND INJECTION	23
3. RESULTS AND DISCUSSION	25
3.1 SELECTION OF GROUT FORMULATION	25
3.2 SOIL-PENETRATION TESTS	26
3.2.1 PregROUT Soil-Penetration Tests	26
3.2.2 PostgROUTing Soil-Penetration Tests	28
3.3 VOID VOLUME MEASUREMENTS	29
3.3.1 Preliminary Pressurization Tests	29
3.3.2 Trench Void Volume by Pressurization Tests	31
3.3.3 PostgROUTing Pressurization Tests	36
3.4 TRENCH GROUTING	39
3.5 GROUNDWATER MONITORING RESULTS	45
4. SUMMARY, CONCLUSIONS, AND NEEDS	48

5. FOLLOW-UP STUDIES:	
GROUTING WITH CLAY-MICROFINE-CEMENT (CMFC) GROUTS	52
5.1 CMFC FORMULATION STUDIES	53
5.2 LEACHING STUDIES	55
5.3 TRENCH GROUTING WITH A CMFC GROUT	59
5.3.1 Preparation of CMFC at the Field Site	61
5.3.2 Trench Injection of CMFC	61
5.3.3 Field Testing of CMFC Grouted Trenches	67
6. SUMMARY AND CONCLUSIONS	70
7. REFERENCES	72
APPENDIX A	
Soil penetration data after grouting with Portland Type I cement.	75
APPENDIX B	
Soil penetration data after grouting with CMFC	77
APPENDIX C	
Soil penetration data from trench 148	79

LIST OF FIGURES

Figure		Page
1	Location and topography of burial trenches at the Test Area for Remedial Actions in Solid Waste Storage Area Six.	2
2	Outline of waste trenches at the Test Area for Remedial Action (TARA) site in Solid Waste Storage Area Six (SWSA6). 6	6
3	Locations of soil penetration tests within and outside trenches 170 and 151.	7
4	Photograph of slotted pipe and installed injection well.	8
5	Reaching uniform pressure within trench using constant flow input. ...	13
6	Hydrograph of water elevations during the pump-in tests on trench 6.	17
7	Hydrograph during water pump-in test on trenches 151 and 170.	18
8	An effective or compressed hydrograph of water pump-in test at trenches 151 and 170.	19
9	Grouting module used to inject grout in trenches 151 and 170.	23
10	Summary of pregrouting soil penetration tests inside and outside trench area.	27
11	Pregrout soil penetration results inside trench 170.	27
12	Pregrouting soil penetration results inside trench 151.	28
13	Summary of soil penetration tests.	30
14	Location of trench wells used for pressurization tests.	30
15	Pressurization of trenches 151 and 170 at 40 cfm.	34
16	Pressurization of trenches 151 and 170 at 70 cfm.	34
17	Pressurization of trenches 151 and 170 at 100 cfm.	35

18	Pressurization of trenches 151 and 170 at 130 cfm.	35
19	Location of wells used for post-grouting pressurization tests.	39
20	Pressurization of postgrouted trenches 151 and 170 at a flow rate of 110 cfm.	40
21	Pressurization of postgrouted trenches 151 and 170 at a flow rate of 155 cfm.	40
22	Pressure response in postgrouted trench 151 at a flow rate of 115 cfm.	41
23	Pressure response in post-grouted trench 170 at a flow rate of 105 cfm.	41
24	Leachability index of tritium as a function of time.	58
25	Fraction of tritium leached from selected grout formulations as a function of time.	60
26	The pH of leachate generated from three grout formulations during the ANS-16.1 leaching test.	60
27	Preparation of the grout formulation using a cyclonic mixer and grouting unit the field site.	62
28	Location of wells used to inject grout into trench 148.	66
29	Locations within trenches 148, 151, and 170 where hydraulic conductivity measurements were taken.	68
30	Trench 148 soil penetration tests.	69

LIST OF TABLES

Table		Page
1	Depth of injection wells	8
2	Depth and length of screen in wells of post-grouted trenches	10
3	Void-volume measurements conducted using CO ₂ injection or N ₂ pressurization techniques	11
4	Summary of calculations of water-accessible void volumes derived from trench water pump-in tests	16
5	Chemical analyses typical of fly ashes and cements tested for grout formulation	21
6	Results of laboratory grout tests	25
7	Grout formulation penetration-resistance results	26
8	Summary of pregrouting soil-penetration tests in trenches 151 and 170	29
9	Preliminary pressurization data ^a	31
10	Pressurization constants and trench void volumes for four inflow rates used in TARA trench pressurization tests	33
11	Trench pressures developed by injecting air into well P-16 of trench 151	37
12	Trench pressures developed by injecting air into well P-2 of trench 170	38
13	Postgrouted trench void volumes estimated by the pressurization technique	42
14	Operational description of grouting trench 170	43
15	Operational description of grouting trench 151	44
16	Radioactivity in water sampled from wells 165-NW and 165-SW before and after grouting	45

17	Concentrations of metals (mg/L) in water	47
18	Estimated material costs for various grouting scenarios	51
19	Properties and composition of microfine cements	52
20	Fluidity of grout as influenced by chemicals added	54
21	Fluidity and penetrability of grouts	55
22	Description of grouting formulations	58
23	Leachability indexes measured for three grout formulations	59
24	Field grouting notes	63
25	Measurements of hydraulic conductivity within and adjacent to the trenches	69

ABSTRACT

In Situ Grouting of Low-Level Burial Trenches with a Cement-Based Grout at Oak Ridge National Laboratory. C. W. Francis, R. D. Spence, T. Tamura, and B. P. Spalding. ORNL/TM-11838, Oak Ridge National Laboratory, Oak Ridge, Tennessee.

A restoration technology being evaluated for use in the closure of one of the low-level radwaste burial grounds at Oak Ridge National Laboratory (ORNL) is trench stabilization using a cement-based grout. To demonstrate the applicability and effectiveness of this technology, two interconnecting trenches in Solid Waste Storage Area 6 (SWSA6) were selected as candidates for in situ grouting with a particulate grout. The trenches are ~15 ft deep and measure 38 by 14 ft and 47 by 14 ft. The primary objective was to demonstrate the increased trench stability and decreased potential for leachate migration following in situ injection of a particulate grout into the waste trenches. Stability against trench subsidence is a critical issue. For example, construction of impermeable covers over the trenches will be ineffective unless subsequent trench subsidence is permanently suspended.

Before the trenches were grouted, the primary characteristics relating to physical stability, hydraulic conductivity, and void volume of the trenches were determined. Before grouting, soil penetration tests revealed that at soil depths >5 and <15 ft, mean blows per foot within the trench averaged ~20 blows per foot below that outside the trench, implying that considerable uncompacted soil and/or void space existed within the trench area which over time will lead to significant subsidence of the upper soil layers. Hydraulic conductivity tests within the trench area also revealed a high potential for the infiltration of water (hydraulic conductivities >0.1 cm/s).

Void volume within the trenches was determined by two techniques: (1) water-pump tests and (2) a newly developed air-pressurization technique. Estimates of void volume using the air pressurization technique were ~ twice that determined by the water-pump test (230 yd³ vs 115 yd³). The void volume determined by the water pump test most likely represents the void volume that could be realistically filled by grout. Also, this test contained a correction for the quantity of water observed in adjacent trenches whereas the pressurization tests did not involve measurements of pressures in the adjacent trenches. The development of the air pressurization technique was pursued because water-pump testing may result in serious leaching of radionuclides and/or hazardous wastes into groundwater and induce premature settling of soil overburden into the trench.

After grouting, soil-penetration tests disclosed that stability had been improved greatly. For example, refusal (defined as >100 blows to penetrate to a depth of 1 ft) was encountered in 17 of the 22 tests conducted within the trench area. Mean refusal

depths for two trenches were 11.5 and 8.5 ft, respectively. The postgrout soil-penetration tests revealed that the stability of the trench was significantly better than pregrout conditions, and at depths >8 ft, the stability was very near that observed in the native soil formation outside the trench. The major differences in results between postgrouting tests and tests conducted in native soil formations outside the trench were found at soil depths of 6, 7, and 8 ft. Tests within the trench showed lower stability within this range probably because of the presence of intermediate-size soil voids (formed during backfilling) that were too small to be penetrated and filled by the conventional cement grout formulation. Hydraulic conductivity within the trench remained very high (>0.1 cm/s) and significantly higher than outside the trench. Postgrouting air-pressurization tests also revealed a large degree of intervoid linkage within and between the two trenches. Thus, it appears that to effectively reduce hydraulic conductivity and to develop stability within the upper level of the trench it may be necessary to implement additional stabilization techniques. One possibility is the injection of a chemical or microfine cement grout into the upper level of the grouted trench.

In follow-up studies conducted during the summer of 1991, the same two trenches previously grouted with the Portland Type I cement-based grout, were grouted again with another particulate-based grout made from a microfine cement (a fine grained cement >50% by weight to be <5 μ m diam) and Wyoming bentonite to fill the unfilled void spaces and reduce hydraulic conductivity within these trenches. The same clay-microfine-cement (CMFC) grout was also injected into a another trench.

Approximately 12 yd³ of the CMFC was injected into the previously grouted trenches with the expressed purpose of lowering hydraulic conductivity within these trenches. Measurements of hydraulic conductivity after grouting with the CMFC grout averaged 1.2×10^{-3} cm/s, considerably higher than average hydraulic conductivity in soil outside the trenches (6.4×10^{-5} cm/s). Thus, these data indicate grouting with the clay-microfine cement did not reduce hydraulic conductivity to levels commonly observed in surrounding soils. The average hydraulic conductivity measured in the CMFC grouted trench was approximately the same as that measured in the grouted 151 and 170 trenches (1.7×10^{-3} cm/s) and much higher than the average measured in the surrounding soils, again indicating grouting with the CMFC grout did not appreciably lower hydraulic conductivity measurements in the trench. In addition, trench stability was not increased using the CMFC grout. For example, soil-penetration data before and after grouting with the CMFC grout revealed no significant difference ($P < 0.5$) in the number of blows to penetrate the distance of one foot indicating no benefits in increased trench stability from the CMFC grout.

These in-situ grouting studies of low-level burial trenches with cement-based grouts (using Portland Type I cement) have shown considerable benefit in increasing trench stability against potential future subsistence; however, little effect can be

expected with regard to lowering hydraulic conductivity within the trenches, even if clay-based microfine cements are used as grouting materials.

1. INTRODUCTION

Oak Ridge National Laboratory (ORNL) has recently finished placing an interim covering ~10 acres of Solid Waste Storage Area 6 (SWSA 6), where low-level radioactive wastes (LLRW) have been buried in shallow trenches (Bechtel 1988; Lockwood Greene 1988). The final closure of SWSA 6 awaits the completion of its remedial investigation into the nature and extent of contamination as well as the development of effective and safe techniques to stabilize the burial trenches. To select trench stabilization and closure alternatives, a group of 19 burial trenches in SWSA 6 was identified as a demonstration and test area to (1) identify promising trench stabilization and closure techniques applicable to the ORNL setting, (2) carry out these techniques on a field scale in actual LLRW trenches, and (3) collect the necessary data to evaluate each technique relative to its feasibility, effectiveness, and cost.

This project, called Test Area for Remedial Actions (TARA), is being conducted on a small hillock in the northeastern corner of SWSA 6 (Spalding et al. 1989, see Fig. 1). The site was selected primarily on the basis of the following two criteria: (1) it is away from daily waste management activities and most important (2) it is located entirely on high ground and is isolated hydrologically from any peripheral recharge areas that would complicate formulating a site water budget and conducting performance monitoring as part of the stabilization/closure evaluations. The water table at the site is at least 20 ft below the bottoms of the trenches, and the trenches in the area are, therefore, unsaturated throughout the majority of the year in contrast to being chronically seasonally inundated, as is the case with other trench areas within SWSA 6.

Two stabilization and closure technologies have been demonstrated at this site. Five burial trenches have undergone a dynamic compaction demonstration (Spalding et al. 1989), and two have been grouted by the in situ injection of a polyacrylamide chemical grout (B. P. Spalding and Fontaine 1992). Dynamic compaction is quite effective in improving the stability of SWSA 6 burial trenches (Spalding 1986), and in situ grouting with polyacrylamide significantly reduces the hydrologic conductivity within the trench (Spalding et al. 1987). Final closure requires sufficient stability within the trench area to ensure that subsidence will not occur after construction of trench caps and moisture barrier controls. Dynamic compaction appears to be a relatively inexpensive stabilization approach. On the other hand, in situ grouting of uncompacted trenches with polyacrylamide appears to be expensive because of the cost of the acrylamide grouting materials (\$2/gal) and relatively large volume voids of uncompacted trenches (estimated cost is ~\$50,000 per typical burial trench). However, if the two are combined (i.e., dynamic compaction followed by in situ grouting with acrylamide), the costs involved would be much less because ~80% of the trench void volume is reduced by dynamic compaction. Demonstration tests conducted during September and October of 1989 revealed that the low hydrologic conductivity of compacted trenches limited the mobility of the acrylamide monomer and its setting catalysis to such an extent that in situ grouting




Fig. 1. Location and topography of burial trenches at the Test Area for Remedial Actions in Solid Waste Storage Area 6.

of compacted trenches was not possible (B. P. Spalding, ESD, ORNL, personal communication to B. P. Spalding, ESD, ORNL, November 1989).

Implementation of either stabilization technology—dynamic compaction or in situ grouting with acrylamide—may also present serious environmental and safety consequences. Of most concern is the improper use of acrylamide, a toxic substance and suspected carcinogen. It poses a risk to those who prepare and inject the grout; also if conditions exist in the trench that inhibit polymerization, it might contaminate groundwater used for drinking and there by pose a potential health hazard. After acrylamide polymerizes (viz, after the grout sets), it becomes nontoxic and nonhazardous. Hence, the ability to control the polymerization process (i.e., set time) after injection into the burial trenches is paramount in order to ensure that the process will not result in groundwater contamination. In many cases, considerable testing may be required to make certain that set time is not adversely affected by the inorganic and/or organic constituents contained in the waste trenches. These assurances will probably have to be demonstrated and documented before federal and state regulatory agencies grant the approval to implement.

Dynamic compaction on trenches in SWSA 6 also presents some unique safety and environmental concerns. For example, resuspension of contaminated soil presents a potential risk with respect to the inhalation, ingestion, and absorption of radionuclides or toxic chemicals by site personnel. Even though previous demonstrations have shown this is not a significant concern, precautions and rigid safety rules need to be followed when the technique is used. Because some of the burial trenches in SWSA 6 hold incidental but unquantified amounts of contained liquids, some of which may be toxic and hazardous, the environmental impact on groundwater as these liquids are released during the dynamic compaction process is inherently unpredictable. Also, many of the trenches in SWSA 6 are inundated with groundwater either seasonally or chronically (Solomon et al. 1988). Thus, many of the trenches will have to be dewatered, and the influence of dynamic compaction needs to be determined on these trenches containing soil backfill near field saturation. The chief issue at hand is the ability to demonstrate the recovery of liquid released during compaction.

Because of the (1) high costs associated with in situ grouting of acrylamide in uncompacted trenches, (2) the inability to use the acrylamide in situ grouting technique at dynamically compacted trenches, and (3) the unresolved questions relating to the release of contained liquids during dynamic compaction of burial trenches, the U.S. Department of Energy (DOE) has asked ORNL to demonstrate if in situ grouting with a particulate-based grout is a viable alternative that will provide long-term burial trench stability (Tom Wheeler, DOE Oak Ridge Operations Manager for the ORNL Environmental Restoration Program personal communication to Ken Cook, program manager for ORNL Remedial Action Program, July 25, 1989).

ORNL has previously conducted demonstrations using particulate grout in waste

trenches (Tamura et al. 1987; Davis and Spalding 1986). Davis and Spalding (1986) used a particulate grout (cement-bentonite) to grout an opened (new) trench and compared its effectiveness in isolating waste hydrologically with that of Hypalon (a reinforced chlorosulfonated polyethylene fabric). The researchers concluded that the cement-bentonite grouting treatment offered a higher degree of waste isolation than did the lining technique. Tamura et al. (1987) injected a particulate type grout made of cement, fly ash, and bentonite into a LLRW trench in SWSA 6. The demonstration revealed that a cement-based grout could be successfully formulated and pressure-injected into a SWSA 6 waste trench. Thirty-six injection wells (2-in.-diam lances made of Schedule 80 steel pipe) were installed at 5-ft centers in a trench measuring 56 ft long, 9 ft wide, and 12 ft deep. Five of the injection wells took 78% of the grout injected, which indicated that grout mobility within the trench was not greatly restricted. The average pumping rate was 6.1 gpm at a pressure range of 5 to 10 psi. The total volume of grout injected was 8081 gal (~9% more than the measured void volume). Void volume within the trench was estimated to have been reduced three orders of magnitude; however, pumping tests with water revealed significant movement of water between injection wells within individual areas of the trench. Postgrouting penetration test results were conducted but were compared with those of penetration tests conducted on an adjacent ungrouted waste trench rather than on the pregrouted waste trench. These tests revealed the denser nature of the grouted trench compared with bordering ungrouted trench.

To validate this observation, the present demonstration involving the grouting of a SWSA 6 trench with particulate grout has been conducted. In this demonstration, penetration tests were conducted within the trench area before as well as after grouting. The primary objective of this task is to demonstrate the feasibility and effectiveness of the in situ injection of a particulate grout into waste burial trenches. Effectiveness is defined here as increased trench stability (characterized by soil-penetration tests) and decreased potential for leachate migration (characterized by hydraulic conductivity tests).

2. METHODS AND MATERIALS

2.1 SITE DESCRIPTION

Two trenches, Nos. 151 and 170 in the TARA site (Fig. 2), were selected as candidates for in situ grouting with a particulate grout. The locations of both of these trenches have been surveyed and the corners of each marked. Each of the trenches are ~15 ft deep. Trench 151 measures 42 by 14 ft (~583 ft²) and trench 170 measures 44 by 14 ft (~612 ft²). The two trenches are interconnected; the south end of trench 170 overlaps into the north side of trench 151 (see Fig. 2). These trenches were selected for grouting for two reasons:

1. The void volume of each has been determined by filling with water, and there have been limited measurements of soil penetration within and adjacent the trenches.
2. The water table is ~20 to 30 ft below the bottoms of the trench and thus the trenches are unsaturated throughout most of the year, except possibly after an extended heavy rain in which case water may accumulate for a short time in the bottom of the trenches.

2.2 SOIL-PENETRATION TESTS

A nonstandard penetration test has been developed for use over trenches to avoid auguring contaminated waste to the surface as would result if the standard ASTM (D 1586-84) soil-penetration test were used. The nonstandard test uses a 140-lb drill-rig-mounted drop hammer to drive a 2-in.-diam 60° cone point attached to a 1.75-in.-diam drill rod into the ground. The drill rod is marked at 1-ft lengths, and penetration is measured by the number of blows required to move the device 1 ft into the ground. In January 1990, 12 penetration tests were conducted in trench 170, and ten tests were conducted in trench 151 (Fig. 3). Holes from the penetration test were used to insert casings which in turn were used both to conduct pregrouting hydraulic conductivity tests and to serve as injection wells for pumping grout into the trench. In addition to those penetration tests within trenches 170 and 151, penetration tests were conducted outside the perimeter of the two trenches (see Fig. 3).

2.3 INSTALLATION OF INJECTION WELLS

The previous particulate grouting demonstration (Tamura et al. 1987) used lances made of 2-in.-diam Schedule 80 steel pipe as injection wells. These were placed at ~5-ft centers over the surface of the trench (total of 36 injection wells). The lances




Fig. 2. Outline of waste trenches at the Test Area for Remedial Action (TARA) site in Solid Waste Storage Area Six (SWSA6).

were driven by a 120-lb portable air-driven hammer either to the bottom of the trench or until an obstruction was encountered. Once in place, the lance was pulled up 6 in. and the drive point knocked out of the end for grout injection. When pressures >20 psi or flow rates <6 gal/min were encountered, the lance was then pulled up another 6 in. for additional grout injection. Five injection wells accounted for $\sim 80\%$ of the grout injected, and it was recommended that future demonstrations use fewer injection wells (e.g., injection wells should be based on 20- to 25-ft centers rather than on the 5-ft center that was used). It was also recommended that smaller-diameter pipe be used because of the difficulty in reaching the bottom of the trench. For example, in most instances the lances could not be driven as much as 7 ft. The trench bottom was reached in only 4 out of the 36 injection wells installed.

Several other operational problems were also encountered. For example, because of the 5-ft centers, grout was often pumped directly into one well and out an adjacent well. The poor seal between the lance and surface soil (as a result of moving the lance upward in 6-in. increments during grout injection) often resulted in the breakthrough of grout around the injection wells, even at a relatively low grout injection pressure of 15




Fig. 3. Locations of soil penetration tests within and outside trenches 170 and 151.

to 20 psi.

Several changes were made in the installation of injection wells for this demonstration. The major changes included the use of (1) slotted pipe as injection wells and (2) considerably fewer injection wells [10 to 12 per trench compared with the 36 in the Tamura et al. (1987) study]. Slotted polyvinylchloride (PVC) pipe (threaded and flush-jointed, Schedule 80, 1.25-in. diam) constructed with three rows of 0.1-in.-wide slots (42 slots/ft-row, effective filter area of 11.5 in²/ft) were placed into the holes made during the penetration tests. Solid sections of similar pipe were installed to at least 2 ft below the soil surface. These pipe were obtained from Timco Manufacturing, Inc., Prairie du Sac, Wisconsin. To ensure that injected grout did not return to the surface along the pipe/soil interphase, a 1-ft section of 2-in.-diam pipe was placed over the 1.25-in.-diam pipe and driven into the ground to ~3 in. below the soil surface. A cement-based grout collar was then molded around the surface of the pipe/soil interphase (see Fig. 4).

Several holes made during penetration tests could not be used as injection wells because the drill rods were contaminated to the extent that they were unsafe for handling;

thus, in these cases the drill rods were abandoned in the hole. This was the situation for penetration tests 4, 5, and 9 in trench 170, resulting in only nine wells for trench 170 and ten wells for trench 151 (Table 1). In most cases, the injection wells reached to the bottom of the trench (Table 1). The technique was certainly better in this respect than the technique used by Tamura et al. (1987) in which only 4 of the 36 injection wells reached to the bottom of the trench.




Fig. 4. Photograph of slotted pipe and installed injection well (ORNL 7371-90).

2.4 HYDRAULIC CONDUCTIVITY MEASUREMENTS

2.4.1 PregROUTED TRENCHES

Hydraulic conductivity of pregROUTED trenches was estimated. This was accomplished by pouring 6 L aliquots of water into the slotted injection wells. This technique was chosen because the ORNL Office of Environmental Compliance and Documentation prohibited the use of a constant head pump-test as demonstrated by Spalding et al. (1985). The use of such a technique in the highly permeable pregROUTED trenches would require considerable water; thus, the leaching of contaminants from the trench area would be promoted. Also, Spalding et al. (1985) have collected considerable data demonstrating that the hydraulic conductivity of ungrouted trenches average on the order of 1.5×10^{-2} cm/s.

The tests were conducted in the following manner. First, assume no greater than 13 ft of slotted pipe per injection well (conservative assumption based

Table 1. Depth of injection wells

Trench 151		Trench 170		Outside Trenches	
Well No.	ft	Well No.	ft	Well No.	ft
151-1	15	170-1	15	151-E	12
151-2	13	170-2	15	151-NE	13
151-3	15	170-3	15	151-NW	15
151-4	8	170-6	15	151-S	7
151-5	15	170-7	15	151-SE	7
151-6	11	170-8	15	151-SW	15
151-7	13	170-10	12	151-W	10
151-8	14	170-11	12	170-N	15
151-9	14	170-12	15	170-NW	15
151-10	15			170-SW	5
Mean	13.3	Mean	14.1	Mean	11.4

on well depths listed in Table 1). The area available for entry into the trench for such an injection well would be $\sim 982 \text{ cm}^2$ (filter area for the 1.25-in.-diam pipe is $74 \text{ cm}^2/\text{ft}$). At a hydraulic conductivity of 0.1 cm/s , at least 100 mL would have to pass into the trench area within 1 s. The volume potentially contained in a 15-ft injection well (assuming complete closure) would be 3.62 L. Thus, if it were demonstrated that the well could take 6 L of water over a 23-s period (the maximum flow rate of 6 L of water through the funnel used to deliver water to the injection well), the hydraulic conductivity of the pregrouted trench would be $>0.1 \text{ cm/s}$. Three wells from each of the two trenches were randomly selected and 6 L of water poured into them over a 23-s period. In no case were the well casings filled to overflowing, indicating that the hydraulic conductivity of pregrouted trenches was $>0.1 \text{ cm/s}$ ($\sim 0.8 \text{ cm/s}$, assuming 2.8 L is delivered across a filter area of 982 cm^2 in 23 s).

2.4.2 Postgrouted Trenches

Wells for measuring hydraulic conductivity within the trench area following grouting were installed using the holes made during the postgrouting penetration tests. A total of 22 wells (12 in trench 151 and 10 in trench 170) were installed. Instead of using the 0.1-in.-wide slotted pipe (as in the pregrout injection wells), 0.02-in.-wide slotted pipes were installed (1.25 in. ID, Schedule 80 PVC, see Table 2). The effective filter area for this pipe is $21 \text{ cm}^2/\text{ft}$.

Water was poured into nine of these wells (P-2, P-3, P-4, P-7, P-11, P-17, P-18, P-22, and P-24) to estimate lower limits in hydraulic conductivity and to compare the hydraulic conductivity within the postgrouted trench with that outside the trench. These tests were conducted in a manner similar to those for pregrouted trenches (i.e., 6 L were delivered through a flow cone over a 23-s interval). Only one well failed to take the full 6 L (well P-2, which overflowed after 6 s). On the other hand, two wells outside the trench area (well P-1, which was 15 ft deep with 12 ft of 0.02-in.-wide screen, and well 151-W, a pregrout monitoring well at the west end of trench 151) failed to take 6 L of water in the 23 s which indicates that the hydraulic conductivity within the trench area after grouting was generally $>0.1 \text{ cm/s}$ and appreciably greater than that measured in undisturbed soil outside the trench. For example, mean hydraulic conductivity of undisturbed soil formation at the TARA site in "driven" wells was $1.2 \times 10^{-5} \text{ cm/s}$. Previous measurements in SWSA 6 have resulted in mean hydraulic conductivities of 3.5×10^{-5} and $2.0 \times 10^{-5} \text{ cm/s}$, Luxmoore et al. (1981) and Davis et al. (1984), respectively.

2.5 VOID-VOLUME MEASUREMENTS

The combined void volume of trenches 151 and 170 has previously been determined by filling with water and taking into account losses resulting from seepage

Table 2. Depth and length of screen in wells of post-grouted trenches

Trench 151			Trench 170		
Well No.	Depth ft	Screen ft	Well No.	Depth ft	Screen ft
P-14	14.5	10	P-2	15	12
P-15	11.5	9	P-3	15	12
P-16	14.8	12	P-4	9.2	5
P-17	7.6	5	P-5	5.5	2
P-18	8.9	6	P-6	8.2	5
P-19	8.3	6	P-7	7.7	4
P-20	11.3	7	P-8	9.3	7
P-21	12.7	9	P-9	7.9	5
P-22	11.3	7	P-10	10.4	7
P-23	15	7	P-11	10.2	7
P-24	13.8	7			
P-25	15	7			

into the surrounding soil (see description of water pump-in test in Sect. 2.5.3). This practice may result in serious leaching of radionuclides and/or hazardous wastes into groundwater and induce premature settling of soil overburden into the trench. It also leaves soil within the trench near saturation levels for a significant period of time, which could have an effect on solidification of grout introduced into the trench. Consequently, flooding trenches with water is no longer an acceptable practice for determining trench void volume. Thus, an alternative nondestructive method was needed for determining trench void volume.

A potential nondestructive method for determining trench void volume is based on pressurization of the trench (treating it like a closed but leaky vessel) and calculation of void volume from the ideal gas law. This is the same technique used in the N₂ pressurization of the closed radwaste disposal silo in SWSA 6 (Table 3); however, in this case ambient air (instead of N₂) was pumped into the trench. The trench is obviously not a closed vessel, but experience during grouting exercises has revealed that pressures of ~10 to 15 psi can be achieved. After taking into consideration leak rates (similar to those used in determining trench void volume by flooding with water), void volume can

Table 3. Void-volume measurements conducted using CO₂ injection or N₂ pressurization techniques^a

Technique	CO ₂ or N ₂ influx (ft ³ /min)	Estimated void volume (yd ³)
CO ₂ injection	0.35-0.43	13.5-16.2
	1.02-1.12	13.6-15.1
	1.70-1.79	14.5-15.2
	Mean = 14.7 ± 1.0	
N ₂ pressurization	0.51	14.3
	0.80	14.8
	0.89	17.4
	1.10	17.3
Mean = 16.0 ± 1.6		

^aVoid volume measured in the Solid Waste Storage Area Six (SWSA 6) below-grade radwaste disposal silo, September 1989, by P. J. Hanson and C. W. Francis.

be calculated from the ideal gas law. Validation of such a simple technique to determine trench void volume would be a significant accomplishment. For example, one of the most important criterion in determining the effectiveness of in situ grouting is the extent to which the available void space is filled with grout. To do this, it is imperative that the total void volume of the trench be known. Trenches 151 and 170 were selected for grouting because trench volumes had previously been determined by flooding with water, a technique that can no longer be practiced. Thus, these trenches offered an opportunity to verify the use of alternative methods to determine trench void volume.

2.5.1 Trench Pressurization-Theory

This technique is based on the principle that small pressure differentials (<0.5 psi) can be monitored within the trench as a known rate of gas is pumped into the trench. The technique assumes that the void volume of the trench remains constant and that air leaking from the trench occurs across a constant resistance to air flow. The measurement is based on the ideal gas law, where equation (1) describes conditions in the trench before pressurization, and equation (2) describes conditions in the trench after pressurization to a constant pressure, and

$$V_o = \frac{n_o RT}{P_o} \quad (1)$$

$$V_o = \frac{n_x RT}{P_c} \quad (2)$$

- V_o = void volume of trench,
 n_o = moles of gases initially present in trench,
 R = ideal gas constant,
 T = ambient absolute temperature in trench,
 P_o = pressure initially present in trench (assumed 1 atm),
 P_c = pressure in trench after pressurization to constant pressure, and
 n_x = $n_o + n_l$
 = moles of gases after pressurization, where n_o is equal to the moles of gas initially present and n_l is equal to the net moles of gases added to cause increased pressure to P_c .

Thus, the volume of gas added (V_l) to result in P_c is equal to

$$V_l = \frac{n_l RT}{P_c} \quad (3)$$

Combining Eqs. (1) and (2) and assuming no difference in temperature on pressurization,

$$n_o = \frac{n_l P_o}{P_c - P_o} \quad (4)$$

and substituting Eqs. (1) and (3), respectively for n_o and n_l results in

$$V_o = \frac{V_l P_c}{P_c - P_o} \quad (5)$$

The volume attributed to the pressure change in the trench (V_l) can be determined by monitoring the pressure increase in the trench (gauge pressure in trench, P_{ig}) over the time it takes to develop a constant gauge pressure (P_{cg}) from a constant flow rate of air pumped into the trench (Fig. 5). When the trench is at constant pressure, the outflow (leak rate) is equal to the inflow rate. To illustrate, the pressure in the trench can be expressed mathematically

$$P_{ig} = P_{cg} (1 - e^{-Bt}) \quad (6)$$

where

P_{tg} = the gage pressure in the trench at time (t),

P_{cg} = the constant gage pressure in trench after ∞ time at constant inflow,

B_t = a constant descriptive of the pressure rise in the trench.

If one assumes the outflow rate (F_o) is proportional to pressure differential over time,

$$F_o = F_c(1 - e^{-B_t t}) \quad (7)$$

where

F_c = constant pump rate into trench,

then

$$F_o = \frac{P_{tg}}{P_{cg}} \times F_c \quad (8)$$

from which one can calculate the outflow rate as a function of time. In this case, the outflow rate takes the same form as the pressure change in the trench. From conservation of mass, at any specific time the net flow rate that remains in the trench (F_D) is equal to the flow into the trench (F_c) minus the flow rate out of the trench (F_o). Thus




Fig. 5. Reaching uniform pressure within trench using constant flow input.

from Eq. (8)

$$F_i = F_c e^{-B_1 t} \quad (9)$$

and the volume attributed to the pressure change in the trench (V_1) can be determined by integrating the net flow rate (F_i) with respect to time

$$V_1 = \int F_c e^{-B_1 t} dt = \frac{F_c}{B_1} \quad (10)$$

To implement this technique, compressed air was pumped into each of the trenches using at least three injection wells for each trench. Pressure as a function of time was also monitored in each of the trenches by using pressure gauges installed in at least three monitoring wells for each trench. These data provided estimates for V_1 from which V_o can be calculated from

$$V_o = \frac{V_1 P_c}{P_c - P_o} \quad (11)$$

where V_1 = volume of net inflow, P_c = trench pressure ($P_{cg} + P_o$) at constant inflow, and P_o = initial pressure (1 atm).

2.5.2 Trench Pressurization—Applied

Before any pressurization tests were conducted, the trench air was sampled for volatile organic compounds. Analyses revealed detectable levels of acetone, tetrachloroethene, 1,1,1-trichloroethane, ethylbenzene, styrene, vinyl acetate, trichloroethene, and benzene, none of which were judged to be in hazardous quantities (B. A. Jerome, Industrial Hygiene Department, ORNL to C. W. Francis, ESD, ORNL, June 1990). To conduct the trench pressurization tests, a high-volume compressor (Ingersoll Rand, Model P-185-W-JD, capable of delivering 185 cfm at 100 psi) was used to force air into the trench. However, before any pressurization tests were carried out at the well heads, outgoing trench air was monitored using real-time instrumentation for volatile organic compounds and radionuclides. None was detected.

Pressure at the top of the slotted injection wells was monitored using Magnehelic pressure gages (Model 2010 Dwyer Instruments, Marietta, Georgia) capable of measuring pressure ranges from 0 to 10 in. of water ($\pm 2\%$ accuracy). The compressor was used to pump air into the trenches at rates ranging from 40 to 130 cfm. Air-pumping rates were determined using an in-line flowmeter (Hedland, Model 03228), which was capable

of direct readout of flows ranging from 20 to 220 cfm ($\pm 5\%$ accuracy). Polyvinyl tubing (0.75 in. ID) was used to deliver air to the injection wells. Several configurations were used to pump air into the trenches [single injection at one end of the trenches (injection well 151-10) and in the center of the two trenches (injection well 170-10) in addition to a multiple injection configuration (injection wells 151-1, 151-7, 151-10, 170-1, 170-10, and 170-12, see Fig. 3]. The principle of the technique required monitoring pressure response over time as a constant flow of air was pumped into the trenches (see Fig. 5). Pressure response was measured at four injection wells in each of the two trenches (total of eight wells). Four investigators manually recorded the pressure response over time (this had to be done rather quickly because constant pressure was usually achieved in < 4 min).

2.5.3 Water Pump-In Tests

Trench void volumes can be determined by filling a trench or connected trenches with water (Spalding 1986; Tamura et al. 1987). To determine void volumes by this method, water levels within a burial trench were monitored as the trench was filled with water at a measured pump rate. The trench can be divided into several region or depth increments, starting at the trench bottom. Seepage rates out of each trench region can be calculated from the time of recession of water level as the trench drains. A seepage rate for each region can be calculated as

$$X_s = \frac{X_f T_f}{T_s + T_f} \quad (12)$$

where

$$\begin{aligned} X_s &= \text{seepage rate, yd}^3/\text{h,} \\ X_f &= \text{water delivery rate, yd}^3/\text{h,} \\ T_f &= \text{region's filling time, h,} \\ T_s &= \text{region's emptying time, h.} \end{aligned}$$

A net filling rate for each region was then calculated as

$$X_n = X_f - X_s \quad (13)$$

where

$$\begin{aligned} X_n &= \text{net filling rate, yd}^3/\text{h} \\ X_f &= \text{water delivery rate, yd}^3/\text{h} \\ X_s &= \text{seepage rate, yd}^3/\text{h.} \end{aligned}$$

Finally, the region void volume was calculated as

$$V_f = X_f T_f - X_s T_s \quad (14)$$

where

V_f = void volume of the region, yd³.

The regional void volumes were then summed to yield the total water-accessible trench void volume, and this, in turn, was expressed as a percentage of the total trench volume. Table 4 summarizes the calculations of water-accessible trench void volumes made for

Table 4. Summary of calculations of water-accessible void volumes derived from trench water pump-in tests

Region	Elevation		Region height ft	Flow rate yd ³ /h	Region fill time h	Region empty time h	Seep rate yd ³ /h	Net fill rate yd ³ /h	Void volume	
	Bottom	Top							yd ³	%
	ft	ft							X_f	X_s
Trench 6										
1	826.56	829.84	3.28	4.09	2.25	41.25	0.21	3.88	8.74	11.74
2	829.84	833.12	3.28	4.09	4.25	20.75	0.69	3.40	14.44	19.40
3	833.12	836.40	3.28	4.09	5.00	13.65	1.10	3.00	14.98	20.13
4	836.40	840.04	3.64	4.09	4.25	3.50	2.25	1.84	7.86	9.51
Total			13.48						46.01	15.04
Trenches 151 and 170										
1	824.46	828.59	4.13	5.65	13.67	150.87	0.47	5.18	70.75	38.63
2	828.59	833.25	4.66	5.56	24.03	9.66	3.96	1.60	38.28	19.65
3	833.25	834.86	1.61	11.14	2.98	0.72	8.99	2.16	6.46	9.07
Total			10.40						115.49	25.06

burial trenches 6 and 151/170 using this method.

Water was pumped from the emergency waste-holding basin to the north of the TARA site into the burial trenches. Trench 6 was filled between October 28 and November 2, 1987, and received 72 yd³ (14,440 gal) of water. Trenches 151 and 170 were filled between August 3 and 6, 1987 and received 362 yd³ (73,103 gal) of water. Water was delivered to the trenches through a 2.5-cm rubber hose run to the bottom of one of the intratrench wells. The water delivery was allowed to continue overnight under continuous surveillance until water level monitoring in additional intratrench wells indicated that the water was within 1.5 ft of the ground surface. When the pump was turned off, the water levels in the observation wells were monitored periodically until the trench was completely drained. This made possible the determination of seepage rates required to correct for seepage during the water delivery interval. Water levels, or more frequently the lack of standing water, in neighboring trenches were also monitored during the filling and draining intervals to identify any hydrologic connection among the burial trenches.

The pump-in test on trench 6 approached an ideal situation (Fig. 6). The pumping rate during filling was quite constant and uninterrupted. Water levels in the three wells, distributed over the length of the trench, rose and fell very uniformly. Not all these wells penetrated completely to the trench bottom; therefore, water levels did not recede




Fig. 6. Hydrograph of water elevations during the pump-in tests on trench 6.

below a small cup in the bottom of the well casings. Although not shown, water levels in nearby burial trenches, notably trenches 5 and 7 (Fig. 1) were not observed during trench filling or recession which indicates that water was not filling voids other than in trench 6.

In contrast, the pump-in test of trenches 151 and 170 (Fig. 7) was not as ideal as that obtained on trench 6. The pumping rate was not uniform; the pump actually stopped for several hours between late-night and early-morning checks. Later the water delivery line began to leak, and the pumping rate, as measured at the wellhead, declined. Adjustments of pump speed were made in an attempt to maintain a constant delivery rate, but the leak became progressively more serious, and finally a section of the line had to be replaced. However, at this point the rate of trench filling was such that to avoid having to terminate pumping and monitor water levels at short intervals during the middle of the night, pumping was accelerated by the addition of a second pump, with the concomitant doubling of delivery rates, for several hours near the end of trench filling.

In addition, water levels for two of the three monitoring wells in trench 151, into which water was pumped, exhibited a lag compared with the well nearest the point of discharge (T151A). The well in trench 170 (T170) exhibited an even more pronounced lag. When the pumps were turned off, water levels within trenches 151 and 170 became uniform during recession. Unlike the trench 6 test, water was observed in adjacent




Fig. 7. Hydrograph during water pump-in test on trenches 151 and 170.

trenches, particularly trenches 148 and 159. However, trench 159 did not exhibit a measurable water level until after the pump was turned off. Trench 148 did, however, exhibit about a 6-ft rise in water level, indicating that it contributed a significant fraction to the measured void volume (Table 4). However, because of the nature of the void calculation, the pumping aberrations can be disregarded and an effective filling hydrograph (Fig. 8) can be used to determine filling and emptying times and pumping rates.

The "measured" voids in trenches 151 and 170 amounted to 115 yd³ (23,328 gal). However, this volume does not include the top region of trench 170 between 832.4 and 834.7 ft above National Geodetic Vertical Datum (NGVD), but it does include voids in trench 148 between 824.3 and 829.2 ft above NGVD. Thus, the measured voids in trenches 150 and 170 are estimated to be within $\pm 20\%$ of the calculated amount. Interestingly, the distribution of voids with depth in trenches 6 and 150 and 170 offered some contrast. Most of the voids in trenches 150 and 170 were in the bottom half trench regions, and the lowermost 4-ft region contained 38% voids. In contrast, trench 6 exhibited about 12% voids in the lowermost region and was more uniform in distribution of percentage of voids with depth. This large void volume in the lower part of trenches 150 and 170 may explain the frequent encounter with penetration resistant material at this depth below the ground surface after filling the trench with grout.




Fig. 8. An effective or compressed hydrograph of water pump-in test at trenches 151 and 170.

2.6 GROUNDWATER MONITORING

The water table at this site is ~20 ft below the bottoms of the trenches. In June 1990 the only wells inside or outside the trench area to contain water were wells 165-NW and 165-SW. With the use of a peristaltic pump and Teflon tubing, water samples were collected from these wells on June 20, 1991, (before grouting) and February 8, 1991, (after grouting). The quantity sampled from either of the two wells on either of the sampling dates was <500 mL because of the slow recharge to the wells. Water taken from these wells is seepage water collected in the bottom of the wells following heavy rainfalls. The permanent water table is >15 ft below the bottom of these wells. These samples were acidified to pH <2 using Ultrex nitric acid and analyzed (without filtration) for radioactivity (gross alpha and beta and ⁹⁰Sr concentrations using EPA methods 900 and 905, respectively). Concentrations of metals were determined by Inductive Coupled Plasma spectrometry (EPA method 200.7).

2.7 GROUT FORMULATION AND TESTING

The performance criteria established for grout formulation were the same as that used by Tamura et al. (1987):

Apparent viscosity	< 50 cP
10-min gel strength	< 100 lb _f /100 ft ²
28-d phase separation	0 volume %
28-d compressive strength	> 60 psi

Other tests included penetration resistance and consistency.

The dry solid materials used to develop the grout formulation included the following: two cements (a Type 1 Portland cement obtained from Dixie Cement Company, Knoxville, Tennessee, and a microfine grade of cement produced by kilning finely ground blast-furnace slag, which is merchandized as MC-100 by Geochemical Corporation, Ridgewood, New Jersey), two coal-fired utility fly ashes (an ASTM Class F ash from Owensboro, Kentucky, and an ASTM Class C fly ash from Rockport, Illinois), and a cement-grade Wyoming bentonite (CAS No. 1318-93-0, 80% passing a 200 mesh screen) from Wyo-Ben, Inc., Billings, Montana. Data in Table 5 characteristically represent the chemical analyses of the fly ashes and cements. Three blends were tested: one for each of the fly ashes mixed at 39%_w Type I Portland cement, 55%_w fly ash, and 5.5%_w Wyoming bentonite, and one using 100%_w MC-100 cement. Blends 1 and 2 contained class C and F, respectively, and blend 3 contained the MC-100 cement. The weight of dry solids added to a given volume of liquid (the mix ratio) for grouts containing the fly ashes was 12.0 to 12.5 lb/gal, and a mix ratio of 7.5 to 8.0 lb/gal was used for the grouts made with the MC-100 microfine cement. The standardized test procedures as indicated in the following were all performed in triplicate.

2.7.1 Phase Separation Tests

Phase separation refers to a separate liquid or water phase that collects at the top of a freshly mixed grout. With proper formulation, the volume of liquid is usually found to increase for a short period (1 d) after the grout is mixed and then to decrease to dryness with additional cure time. The volume of liquid was determined by a settling test in a 250-mL graduated cylinder (Tallent et al. 1987). A known volume of freshly mixed grout is poured into the cylinder; then the cylinder is capped and allowed to stand for the time intervals of interest (typically, up to 28 d).

The phase separation (in vol %) is calculated as the volume of clear drainable surface liquid (hereafter referred to as drainable water) divided by the original grout volume.

The method (based on the standardized ASTM C192-81 procedure) for preparing grouts for the phase separation tests in which blends 1 and 2 were used are as follows: The appropriate weight of a given dry solid blend was added to 1.0 L of water containing 0.300 g of delta-gluconolactone (sugar) in a Hobart Model N-50 mixer. The solids-to-water ratio was 12 lb/gal. The addition was made over a period of 30 s at low mixer speed (setting 1). The mixing was continued at low speed for another 30 s and then increased to medium speed (setting 2) for another 30 s. The procedure for blend 3 (100% MC-100 cement) was different in that 85.25 mL of a 50% NaOH solution and 9.5 mL of CA-600 dispersant (marketed by Geochemical Corporation, Ridgewood, New Jersey) were added to 1250 mL of water, and the appropriate weight of the blend added. The mixing times were identical to those for grouts prepared using blends 1 and 2.

2.7.2 Compressive Strength Tests

Compressive strength is a measure of the ability of cured grout to support an applied axial load. Low compressive strength (allowing easy crushing) usually corresponds to more porous grout with the possibility of increased leaching compared

Table 5. Chemical analyses typical of fly ashes and cements tested for grout formulation

Oxide	Fly ash		Cement	
	Class C	Class F	MC-100 ^a	Type 1
	% _w			
SiO ₂	50.5	45.0	31.8	21.0
Al ₂ O ₃	17.2	22.3	15.1	4.6
Fe ₂ O ₃	5.9	5.5	0.7	3.0
CaO	15.8	11.1	41.1	64.1
MgO	3.1	2.0	7.3	2.4
SO ₃	1.0	0.1	2.0	2.7
Na ₂ O	0.5	4.8	0.1	0.2
K ₂ O	0.8	3.8	0.2	0.2

^aMC-100 microfine cement is a finely ground blast-furnace slag.

with grouts having high compressive strengths. The specimens for unconfined compressive strength tests were prepared by pouring freshly prepared grout into 2-in.-cube stainless steel molds and allowing the molds to stay in a humidity cabinet (90 % relative humidity) at room temperature for 28 d. Crushing strengths of the grout cubes were then determined by using a Model 60,000, Super "L" Tinius-Olsen Testing Machine. The freshly mixed grouts were prepared following the same procedure as that used for the drainable water tests.

2.7.3 Penetration Resistance

Penetration resistance is a method used to measure cementitious setting progress as a function of time. Measurements were made using an ACME Penetrometer apparatus from Humboldt Manufacturing Company. Grouts for the measurements were prepared using the same procedure as that used for the phase separation tests. Samples of the grouts, 130-mL volumes, were poured into PVC cups, and the penetration resistance measurements were made at time intervals until setting occurred.

2.7.4 Apparent Viscosity

Viscosity of a grout (a non-Newtonian fluid) varies with shear rate. In these tests the viscosity was measured at 300 rpm with a Fann Direct Reading Viscometer, Model 135A. This viscosity is commonly referred to as apparent viscosity.

2.7.5 Gel Strength

The 10-min gel strength is indicative of the force required to restart the flow of grout after it has remained stationary for 10 min. The measurement is made in the Fann Viscometer with the same grout sample following other rheological measurements. After the grout has been allowed to stand in the viscometer for 10 min without stirring, the instrument is turned on with the shear rate set at 3.0 rpm. The 10-min gel strength in lbs/100 ft² is read directly from the viscometer at the maximum deflection on the shear stress scale.

2.7.6 Consistency

The viscosity or consistency of freshly prepared grout varies as a function of time but usually remains fairly constant for a few hours after mixing and then increases rapidly as hydration reactions and setting processes begin. Consistency was determined by using a Model 123 Cement Consistometer from Halliburton Services.

2.8 FIELD GROUT MIXING AND INJECTION

Grout solids were dry-blended (using existing equipment at the New Hydrofracture Facility) and then mixed with water in a concrete mixing truck. Each truck-load contained 6.33 tons of dry blend (2.47, 3.52, and 0.35 tons of cement, fly ash, and clay, respectively) and 1000 gal of water containing 1 lb of delta gluconolactone (used as a dispersant and set retarder for the grout). The density of the grout was 13.5 lb/gal; thus, each truck-load contained ~ 7.7 yd³. Grout from the concrete mixing truck was transferred to the grouting module using a grout pump furnished by Con-Quip, Inc., Maryville, Tennessee. The grouting module was designed and constructed at ORNL in 1982 (ORNL engineering drawing No. J3DI2534). The module contains two 500-gal mixing tanks (each with single propeller lighting mixers) and two progressive cavity pumps capable of pumping 30 gpm of grout at pressures up to 200 psi (see Fig. 9). One of the two pumps was used to pump grout from the grouting module via 1-in.-diam. high-pressure hose to a single injection well. Pressure at the grouting module was maintained manually at levels ranging from 50 to 100 psi. Grouting pressure at the injection well was usually < 10 psi; however, as the available void space became full of grout, pressures up to 50 and 75 psi were observed, making it necessary to move to another injection well.




Fig. 9. Grouting module used to inject grout in trenches 151 and 170.

3. RESULTS AND DISCUSSION

3.1 SELECTION OF GROUT FORMULATION

Prototype development of grouting formulation was conducted by T. Tamura. Three blends were recommended for testing. Grouts made from each of the three blends met or exceeded established criteria (Table 6). Along with the criteria listed in Table 6 two additional criteria, penetration resistance and fluid consistency, were tested. If one assumes that penetration resistance readings in excess of 4000 psi reflect complete setting of cements, then all three blends set in <3 d (Table 7). Results from the consistometer tests revealed that grouts made from the Class F fly ash possessed a considerably longer field time before setting began. For example, the data indicated that grouts made from

Table 6. Results of laboratory grout tests

Parameter	Criteria	Blend ^a		
		1	2	3
Apparent viscosity	<50 cP	35±1	37±1	10±1
10-min gel strength	<100 lb _f /100 ft ²	30±3	28±7	7±1
28-d phase separation	0 vol%	0	0	0
28-d compressive strength	>60 psi	1601±17	908±28	2000±253

^aBlend 1 contained 39% Type 1 Portland cement, 55.5% Class C fly ash, and 5.5% bentonite mixed at 12–12.5 lb/gal of water. Blend 2 contained 39% Type 1 Portland cement, 55.5% Class F fly ash, and 5.5% bentonite mixed at 12–12.5 lb/gal of water. Blend 3 contained 100% MC-100 microfine cement mixed at 7.5–8.0 lb/gal of water.

Class F fly ash could be pumped for periods up to 7 to 8 h, whereas grouts made of the Class C fly ash may display considerable thickening that would inhibit pumping at periods longer than 5 to 6 h. Grouts made from the microfine cement displayed substantially less consistency (bearden units <5) during the first 6 h compared with grouts made of fly ash (bearden units >10). The addition of 0.02% delta-gluconolactone to the water used to make the microfine cement grouts extended pumping times from 4 to 10 h. Because of the longer pumping times of grouts made from Class F fly ash compared with those of the Class C fly ash, it was recommended that the grout formulation made from the Class F fly ash be used for grouting trenches 151 and 170. The grout made from the microfine cement appeared to be technically acceptable; however, there was concern that it may be difficult to develop sufficient shear to adequately mix this grout formulation in the field using a cement mixer truck. This factor, plus the fact that material costs for the microfine cement grout were on the order

Table 7. Grout formulation penetration-resistance results

Blend tested	Resistance (psi)		
	Day 1	Day 2	Day 3
Blend 1 (Class C fly ash)	453±11	4133±167	>8000
Blend 2 (Class F fly ash)	247±42	>8000	>8000
Blend 3 (Microfine cement)	>8000	>8000	>8000

of ten times higher than conventional cement/fly ash grouts, made the choice of microfine cement less attractive.

3.2 SOIL-PENETRATION TESTS

3.2.1 Pregrout Soil-Penetration Tests

Pregrouting soil-penetration tests within the trench area revealed that as the depth of penetration increased, an increasing number of blows were required to drive the cone farther into the ground (Fig. 10). Mean blows per foot inside the trench area were significantly less than mean blows per foot into soils outside the 151 and 170 trenches. Generally speaking, at soil depths >5 and <15 ft, mean blows per foot within the trench averaged on the order of 20 blows per foot below that outside the trench, implying considerable uncompacted soil or void space within the trench area. Plots of the blows per foot with respect to depth illustrate that specific areas within the trench are more compacted than others. For example, test 11 and to some extent test 10 in trench 170 revealed a compacted area near the bottom of the trench where injection of grout may be more difficult than at other locations in the trench (Fig. 11). A similar point could be made about tests 4 and 6 in trench 151 (Fig. 12).

A summary of all pregrouting soil-penetration tests conducted in trenches 151 and 170 is presented in Table 8. Again, tests 4 and 6 in trench 151 (22.3 and 17.5 mean blows per foot, respectively) indicate that injection of grout into the trench at these sites may be more difficult than injection at the southwest end of the trench (tests 9 and 10, see Fig. 3) where mean blows per foot ranged between 5 and 7. On the other hand, the midsection of trench 170 appears to be less compacted than either of the ends. For example, mean blows per foot were <10 for tests 3, 4, 5, 6, and 12, whereas those at either end (tests 1, 2, and 7, 8, 9, 10, and 11, see Fig. 3) were generally >10 (Table 8).




Fig. 10. Summary of pregrouting soil penetration tests inside and outside trench area.




Fig. 11. Pregrout soil penetration results inside trench 170.




Fig. 12. Pregrouting soil penetration results inside trench 151.

3.2.2 Postgrouting Soil-Penetration Tests

In January, 1991, ~6 months following grouting, soil-penetration tests were conducted within and adjacent trenches 151 and 170. These tests, to soil depths of 15 ft (see Table 2), included ten tests within trench 170 and 12 tests within trench 151 (four were also conducted outside of but adjacent to the trenches). Refusal (i.e., >100 blows to penetrate one foot) was encountered in 17 of the 22 tests conducted within the trench area, resulting in mean refusal depths of 11.5 and 8.5 ft in trenches 151 and 170, respectively. Results from the postgrouting soil-penetration tests revealed that the stability of the trench after grouting was significantly better than before grouting, and at depths >8 ft, the stability (measured in terms of soil penetration) was very near that observed outside the trench (Fig. 13). For example, soil penetration in mean blows per foot at depths >8 ft within the trench was very similar to those measured outside the trench.

Pregrouting tests ranged from 10 to 20 mean blows per foot whereas postgrouting tests ranged from 20 to 40 mean blows per foot. Only at soil depths of 6, 7, and 8 ft were there major differences between postgrout tests and tests conducted outside the trench (Fig. 13). The lower stability exhibited in this range (5 to 8 ft) probably reflect the presence of intermediate-size soil voids (formed during backfilling) that were not penetrated by the conventional cement grout formulation. A statistical summary of the soil-penetration tests (before and after grouting as well as those outside the trench area) as a function of soil depth is presented in Appendix A.

Table 8. Summary of pregrouting soil-penetration tests in trenches 151 and 170

Test	Blows per foot							
	Trench 151				Trench 170			
	Mean	Min	Max	SD	Mean	Min	Max	SD
1	13.1	4	24	6.9	9.8	4	20	5.6
2	13.4	4	29	6.5	10.5	4	24	6.1
3	11.3	5	22	5.8	8.4	4	14	2.5
4	22.3	5	72	25.5	7.5	4	11	2.2
5	6.8	4	12	2.2	9.7	3	15	3.5
6	17.5	4	72	19.7	7.3	3	13	2.6
7	12.9	5	40	9.1	10.5	4	33	8.8
8	9.3	5	16	3.5	9.6	5	19	4.2
9	6.9	5	11	2.2	10.9	5	22	4.3
10	5.4	1	11	2.7	9.2	3	18	4.2
11					19.6	7	58	16.1
12					6.9	4	13	2.7

3.3 VOID VOLUME MEASUREMENTS

3.3.1 Preliminary Pressurization Tests

As an alternative to water pump-in tests, an air-pressurization technique was used to compare the accuracy and operational features of the two techniques. Preliminary pressurization tests included a series of tests to determine the extent of intervoid connection between trenches 151 and 170. For example, air was injected at one end of trench 151 (injection well 151-10, see Fig. 14) to determine if pressure differences could be detected in wells at the farther end of trenches 151 and 170. Other tests included air injection in a single well in trench 170 (170-10) and multiple injections at six wells (151-1, 151-7, 151-10, 170-1, 170-10, 170-12). Three flow rates were used in each test to confirm that pressure measured at the monitoring wells was a function of airflow into the trenches (see Table 9).

In most cases, the monitoring wells were the wells constructed as injection wells




Fig. 13. Summary of soil penetration tests.




Fig. 14. Location of trench wells used for pressurization tests.

for grout (see Fig. 3); however, in several instances, air pressures were monitored at existing wells within the trench area (labeled as 151-1E, 151-2E, 151-3E, 170-1E, and 170-2E in Fig. 14). Three of these wells (151-2E, 151-3E, and 170-1) were constructed of 6-in.-diam corrugated steel reaching to the bottom of the trench. The other existing wells were constructed of 2.5-in.-diam. aluminum tubing, also to the bottom of the trenches. The width and interval of slotting or the overall length of screened section for either of these existing well types is unknown. Slotted PVC pipe with solid top sections, similar to that used for the grouting injection wells, were placed into these existing wells. Then a cement-based grout collar was molded to ~1 ft below the ground surface for the purpose of sealing the well.

The pressurization data measured at these wells (Table 9) verified that a direct linkage occurred between the underground void volumes of the two trenches and that changes in flow rates in the range of 30 to 50 cfm would be adequate to detect significant changes in pressure at the well head.

3.3.2 Trench Void Volume by Pressurization Tests

To determine trench void volume using the pressurization technique, it was necessary to determine the pressure change with time as a constant flow of air was

Table 9. Preliminary pressurization data*

Method	Well	Flow rate (cfm)			
		22	35	67	
Single well	151-1	0.2	0.5	1.5	
	151-2E	0.3	0.6	1.5	
	151-3	0.4	0.8	1.8	
	151-10	151-5	0.5	0.8	1.9
	151-6	0.3	0.6	1.7	
	151-7	0.4	0.8	1.8	
	151-8	0.4	0.8	1.8	
	151-9	0.3	0.6	1.6	
	170-1	0.1	0.2	0.6	
	170-6	0.3	0.4	1.2	
		Flow rate (cfm)			
		27	42	56	
Single well	151-1	0.3	0.5	1.1	
	151-5	0.6	0.8	1.4	
	170-10	151-7	0.5	0.7	1.4
	151-10	0.3	0.6	1.2	
	170-1	0.3	0.4	1.0	
	170-2E	0.5	0.8	1.6	
	170-3	0.6	0.9	1.9	
	170-6	0.6	0.9	1.9	
	170-8	0.5	0.8	1.4	
	170-12	0.5	0.9	1.9	
		Flow rate (cfm)			
		9	39	56	
Multiple wells	151-2E	0.1	0.7	1.2	
	151-5	0.3	1.0	1.6	
	151-9	0.1	0.8	1.4	
	151-1	170-2	0.2	0.8	1.3
	151-7	170-2E	0.1	0.8	1.4
	151-10	170-6	0.1	0.7	1.3
	170-1	170-8	0.2	0.6	1.0
	170-10				
170-12					

*Pressure measured in inches of water at the top of the monitoring well.

pumped into the trenches (see Fig. 5). To do this, air was pumped into six injection wells, three in each of the two trenches (one at each end and at the middle of the trenches, wells 151-1, 151-7, and 151-10 and 170-1, 170-10, and 170-12). Pressure was monitored at eight wells, four in each of the two trenches (wells 151-2E, 151-4, 151-5, 151-9, 170-2E, 170-2, 170-6, and 170-12, see Fig. 14).

The gage pressures in trenches 151 and 170 on pressurization at 40, 70, 100, and 130 cfm were recorded with respect to time in Figs. 15 through 18. These data were fitted using a nonlinear least-squares regression technique (NLIN procedure of SAS 1985) to the general equation

$$P_{ig} = P_{cg}(1 - e^{-B_1 t}) \quad (15)$$

where

- P_{ig} = trench gage pressure in inches of water,
- t = time in seconds,
- P_{cg} = constant gage pressure in trench in inches of water,
- B_1 = is a constant descriptive of the pressure rise in the trench.

The value B_1 is used to determine net inflow volume (V_1) that was pumped into the trench from which the trench void volume (V_o) can be determined (see Eqs. 6, 7, and 8 in Sect. 2.5.1). Expressed in the following units, the equations take the following form

$$V_1 = 0.0167 \frac{F_c}{B_1} \quad (16)$$

where

- F_c = constant pump rate in cfm,
- B_1 = coefficient in s^{-1} (as determined by curve fitting NLIN procedure),
- V_1 = net inflow in ft^3 .

Also,

$$V_o = \frac{0.037 V_1 P_{cg} + 15.1 V_1}{P_{cg}} \quad (17)$$

where

- P_{cg} = constant trench gage pressure in inches of water,
- V_o = trench void volume in yd^3 .

The calculated trench void volumes and values for P_{cg} and B_1 are tabulated (Table 10) for each of the flow rates used to determine a pressure rise in the trenches. Calculated trench void volumes varied considerably (range from 229 to 298 yd^3), and all are

Table 10. Pressurization constants and trench void volumes for four inflow rates used in TARA trench pressurization tests

Flow rate (cfm)	P_{cr} (inches of water)	B_l (s^{-1})	V_o (yd^3)
40	0.68	0.0496	298
70	1.31	0.0478	281
100	2.38	0.0460	231
130	3.08	0.0466	229

considerably higher than the 115 yd^3 determined by water pump-in tests. Air pressurization at 100 and 130 cfm gave very similar void volumes, 231 and 229 yd^3 , respectively.

In both of these data sets (at 100- and 130-cfm flow rates), the data appeared to fit better with the regression equation than it did for 40- and 70-cfm tests (see Figs. 15 through 18). Also, the coefficients of variance (%) for the estimates of B_l in the 40- and 70-cfm pressurization tests were 23 and 14%, respectively, compared with 9.4 and 8.8% for the 100- and 130-cfm tests. The simple fact that the range in pressure readings at the 100- and 130-cfm tests (2.4 to 3.0 in. of water) were so much larger than the 40- to 70-cfm tests (<1.3 in. of water) made it easier to record the pressures as a function to time for the higher flow rates. Thus, the 100- and 130-cfm tests probably represent better estimates of the trenches' void volume than do the 40- and 70-cfm tests. It is not clear why the void volume for trenches 151 and 170 determined by the pressurization technique is ~100% higher (230 yd^3) than the 115 yd^3 determined by water pump-in tests. These values expressed in percent void volume are approximately 25 and 49% (for the water-pumping and air-pressurization tests, respectively). These values are based on a trench depth of 10.4 ft from Table 4 and areas of 583 ft^2 and 612 ft^2 for trenches 151 and 170 (a total volume for trenches 151 and 170 of 461 yd^3). However, if one keeps in mind, that both methods involve considerable experimental error and that both are subject to a variety of boundary conditions governed by the conditions of the soil and distribution of pore volumes, the agreement between the two methods may not be so poor.

The void volume determined by the water pump test most likely represents the void volume that could be realistically filled by grout. Also, this test contained a correction for the quantity of water observed in adjacent trenches (viz, trenches 148 and




Fig. 15. Pressurization of trenches 151 and 170 at 40 cfm.




Fig. 16. Pressurization of trenches 151 and 170 at 70 cfm.




Fig. 17. Pressurization of trenches 151 and 170 at 100 cfm.




Fig. 18 Pressurization of trenches 151 and 170 at 130 cfm.

159) whereas the pressurization tests did not involve measurements of pressures in the adjacent trenches.

The air pressurization tests assume that pressures in the adjacent trenches were not in the same population as those measured in trenches 151 and 170 (viz, the pressure responses in adjacent trenches would not fit the pressure response curves illustrated in Figs. 15 through 18). Differences in pressures between selected areas within trench 170 and trench 151 were observed when air was injected into a single well of a trench (Table 9). In most of the cases, lower pressures were observed in wells farther from the well where air was injected. Thus, it would be expected that major differences in pressure responses (much lower and likely undetectable) would have been observed in trenches adjacent to those where air was injected making pressure responses as those illustrated in Figs. 15 through 18 unique to trenches 151 and 170.

However, the water pump test did show a connect between trenches 151 and 170 to trenches 148 and 192. The response to trench 148 was rather strong (a 6 ft rise in water level during the pumping stage, see section 2.5.3). Water responses were also observed in trenches 192 and 165. In these cases, minor levels of water were noted in the bottom of the trenches after pumping water into trenches 151 and 170. Trench 165 was grouted with polyacrylamide prior to air pressurization tests. Thus, during the air pressurization tests, it is possible that there existed a unobstructed connection for air to move freely to trenches 148 and 192 (total trench volume equivalent to $\sim 360 \text{ yd}^3$ assuming a trench depth of 10.4 ft). Assuming this to be the case (viz, the pressure response curves for trenches 148 and 192 to be the same as that observed for trenches 151 and 170), then the percent void volume for all four trenches would be $\sim 28\%$ [$230 \text{ yd}^3 \div$ volume in trenches 151 and 170 (460 yd^3) plus the volume in trenches 148 and 192 (360 yd^3)], a value equivalent to that measured by the pumping tests on trenches 151 and 170 (see Table 4).

The difference between the two tests is that the water test is based on the rate of leakage (which is a function of hydraulic head) from the trench compared to the rate of water pumped into the trench. In the air pressurization test, the outflow rate is assumed to be proportional to the pressure differential over time independent the spatial dimensions of the trench. It is also logical that void volume measurements determined by air would generally be greater than void volumes determined by water in that accessibility to the smaller pores (micro- and meso-pores) would be more limited to water than air because of the higher permeability and lower viscosity of air as compared to water. Most importantly, air being a nonwetting fluid does not exhibit a wetting and drying hysteresis as does water.

3.3.3 Postgrouting Pressurization Tests

Postgrouting pressurization tests were conducted to determine (1) if intervoid

linkage between the two trenches remained after grouting and (2) if sufficient void space remained, could its volume be estimated using the pressurization technique. To do this, wells constructed from the postgrouting soil-penetration tests (Table 2) were used for air-injection and air-pressurization readings. The location of these wells within the trench area is illustrated in Fig. 19.

To evaluate the extent of intervoid linkage within and between the two trenches, compressed air was injected into a well at the far end of either of the two trenches, namely, well P-6 in trench 170 and well P-16 in trench 151 (Fig. 19). Equilibrium pressure readings at the other wells throughout the two trenches and outside the trenches were then recorded at a specific flow rate of air (Tables 11 and 12). Pressures measured at the monitoring wells appear to vary inversely with the distance from the point of injection (i.e., the farther the distance from the injection well the lower the pressure). The mean pressure observed in trench 170 when air was injected in well P-16 of trench 151 was <0.7 in. of water as compared with >10 in. of water at the well adjacent the injection well. A similar relationship held true in trench 151 (mean pressure of 0.26 in. of water) when air was injected in well P-2 of trench 170. However, this phenomenon was not as apparent in pregrouting pressurization tests (see Table 9). For example, the mean pressure difference between the injection trench and adjacent trench was ~ 0.5 in. of water and was not appreciably different from the variation in pressures

Table 11. Trench pressures developed by injecting air into well P-16 of trench 151

Trench 151		Trench 170		Outside Trenches	
Well	Pressure*	Well	Pressure	Well	Pressure
P-14	>10	P-2	0.2	P-1	0.0
P-15	8.3	P-3	0.4	P-12	0.2
P-17	4.0	P-4	0.4	151-W	0.0
P-18	3.1	P-5	0.1	151-SW	0.1
P-19	4.0	P-6	0.6	151-E	0.0
P-20	1.9	P-7	0.3	151-S	0.2
P-21	2.5	P-8	1.0	170-NW	0.0
P-22	1.8	P-9	0.6	165-SW	0.1
P-23	1.8	P-10	1.2		
P-24	1.7	P-11	1.7		
P-25	1.8				

*Flow rate of 90 ft³/min and pressure measured in inches of water at the top of the monitoring well.

Table 12. Trench pressures developed by injecting air into well P-2 of trench 170

Trench 170		Trench 151		Outside Trenches	
Well	Pressure*	Well	Pressure	Well	Pressure
P-3	>10	P-14	0.0	P-1	0.9
P-4	7.8	P-15	0.0	165-NW	2.5
P-5	5.3	P-16	0.2	151-W	0.0
P-6	7.1	P-17	0.2	151-SW	0.1
P-7	6.5	P-18	0.3	151-E	0.0
P-8	3.0	P-19	0.2	165-SW	0.1
P-9	2.5	P-20	0.3		
P-10	2.8	P-21	0.3		
P-11	0.6	P-22	0.4		
		P-23	0.3		
		P-24	0.7		
		P-25	0.2		

*Flow rate of 100 ft³/min and pressure measured in inches of water at the top of the monitoring well.

within a trench. These data support the conclusion that little resistance existed in the flow of air within and between trenches 151 and 170 (highly permeable large void spaces) in the pregrouted trenches; thus, the two trenches respond as a single trench. Grouting appears to have greatly decreased permeability by filling the large voids; however, significant channeling within and between trenches still remains.

An estimate of the void volume remaining in the two trenches after grouting was attempted using the pressurization technique (see Sect. 2.5.1, Trench Pressurization-Theory). To determine void volume of both trenches (151 and 170), air was simultaneously injected into wells P-2, P-7, and P-11 of trench 170 and wells P-14, P-21, and P-25 of trench 151 (Fig. 19). Pressure responses as a function of time were recorded at the other wells at 110 and 155 cfm (see Figs. 20 and 21). To determine void volume within individual trenches (e.g. air was pumped into trench 151 through wells P-14, P-21, and P-25 at a flow rate of 115 cfm). For trench 170, air was pumped into wells P-2, P-7, and P-11 at a flow rate of 105 cfm. Pressure responses were then recorded as a function of time at the other wells (Figs. 22 and 23). Void volumes for these trenches were determined using Eqs. (16) and (17) (Table 13).

A much shorter response time and larger variation in pressures were recorded at the wells of postgrouted trenches than at pregrouted trenches (e.g., compare pressure-response curves of Figs. 15 through 18 with those observed in Figs. 20

through 23). This probably results from the much larger resistance of flow in postgrouted trenches versus pregrouted trenches. The pressure response curves measured in pregrouted trenches closely simulated those of a closed vessel (a single curve regardless of the location measured), the theory on which the technique is based. For example, the pressurization data from the pregrouted tests could be fitted using nonlinear regression procedures with confidence (i.e., coefficients of variance for estimates of B_1 were $< 10\%$ at flow rates > 100 cfm). For postgrouted trenches this was not the case (i.e., coefficients of variance for estimates of B_1 ranged from 10 to 28%). On the other hand, coefficients of variance for estimates of P_{cr} were $< 5\%$. Estimates of total trench void volume (trenches 151 and 170 combined) were 87 and 71 yd^3 , using 110 and 155 cfm flow rates, respectively. Estimates of individual trench void volumes were 37 and 43 yd^3 for trenches 151 and 170, respectively. Thus, the estimate of total trench volume determined by two different flow rates and combined volume determined for each trench independently is on the order of 80 yd^3 . The total trench volume before grouting was estimated to be 230 yd^3 (Table 10). Approximately 79 yd^3 of grout was added to the trenches, leaving on the order of 70 yd^3 of trench volume still available, theoretically. However, it is entirely possible that grouting restricted air movement to this 70 yd^3 that is encapsulated or adjacent to the sides or bottom of the trenches.

3.4 TRENCH GROUTING

Grouting of trench 170 was started on June 26, 1990, and finished on June 29, 1990. Grouting of trench 151 occurred ~ 1 week later, July 7 through July 12, 1990.




Fig. 19. Location of wells used for post-grouting pressurization tests.




Fig. 20. Pressurization of postgrouted trenches 151 and 170 at a flow rate of 110 cfm.

Grout solids were dry-blended at the New Hydrofracture Facility, mixed with water in




Fig. 21. Pressurization of postgrouted trenches 151 and 170 at a flow rate of 155 cfm.




Fig. 22. Pressure response in postgrouted trench 151 at a flow rate of 115 cfm.




Fig. 23. Pressure response in post-grouted trench 170 at a flow rate of 105 cfm.

Table 13. Postgrouted trench void volumes estimated by the pressurization technique

Trench	Flow rate (cfm)	P_{cs} (inches of water)	B_1 (s^{-1})	V_o (yd^3)
151 & 170	110	4.74	0.0683	87
151 & 170	155	6.96	0.081	71
151	115	6.07	0.129	37
170	105	8.25	0.072	43

a redi-mix concrete truck, and transported to SWSA 6. Each truckload contained 7.7 yd^3 (see Sect. 2.8). The grout injection operation proceeded rather smoothly. The single most troublesome operational problem was the plugging of the delivery lines from the grout pump. The plugging most often occurred at the reducer, coupling the 2-in.-diam pipe from the grout pump to the 1-in.-diam high pressure hose used to delivery the grout to the slotted injection wells. Small gravel (0.25 to 0.5 in. diam), probably introduced from the redi-mix truck or chips of dried grout from the mixing tanks initiated the plugging. The line at the reducer couple had to be disconnected and cleaned periodically for continued operation. A summary of the grouting operation for trenches 170 and 151 is outlined in Tables 14 and 15.

One of the problems observed by Tamura et al. (1987) in the grouting of trench 150 in SWSA 6 was leakage or backflow of grout between the lance used to inject grout and the soil. They had used a lance made of 2-in.-diam Schedule 80 steel pipe to inject grout. Unlike the injection wells used in this study, the lance did not have slotted openings to deliver grout. The lance depth was changed by pulling the lance up 1 ft when the grouting pressure exceeded 20 psi or flow rates became <4 gpm. This weakened the seal between the lance and surrounding soil, often resulting in backflow of grout outside and along the lance to the soil surface.

In this study, to ensure that the injected grout did not return to the surface along the pipe/soil interphase, a 1-ft section of 2-in.-diam pipe was placed over the 1.25-in.-diam injection well and driven into the ground to ~3 in. below the soil surface. A cement-based grout collar was then molded around the surface of the well/soil interphase. Injection pressures used in this study were significantly greater (maximum pressure as high as 75 psi), yet breakthrough around an injection well occurred only once (well 8 in trench 151).

A total volume of 79 yd³ of grout was injected into the two trenches (48 and 31 yd³ in trenches 151 and 170, respectively). If one assumes the void volume to be 230 yd³ as determined by the air pressurization tests (Table 10), then 34% of the available void volume was filled with grout. However, if 115 yd³ is taken as the void volume, as determined from water-pump test, then 68% of the void volume was filled with grout.

Trench 170 is the larger of the two trenches, but more grout was injected into trench 151. Assuming the trenches to have an overall depth of 10.4 (as measured by the water pump test, Table 4), the volume of the trenches are 236 and 225 yd³, respectively. In this respect, ~17% of the total volume was filled with grout (21% for trench 151 and 13% for trench 170).

Tamura et al. (1987) injected 40 yd³ into a much smaller trench (Trench 150, measuring 56 x 9.2 x 11.8 ft) whose volume, assuming a 3 ft soil cover, was 152 yd³. On the bases of these measurements, the volume of grout injected would constitute 26% of the trench. However, the final disposition of some of this grout was outside the trench because the breakthrough of grout to the surface was recorded at six to eight areas outside the trench. Also, the quantity of injected grout represented 109% of the measured void volume, indicating the volume of grout injected to be a high estimate. Most important, the void volume available for grouting is dependent on the waste

Table 14. Operational description of grouting trench 170

Date	Time	Truck	Well	Comments
6/26	p.m.	1	1 & 2	When well pressure reached 50 psi, moved to well 2 and pumped remainder of load
6/27	p.m.	2	3 & 12	At 1 p.m. starting pumping into well 3. After 15 min, pressure was > 50 psi. Moved to well 12 and pumped remainder of load
6/28	a.m.	3	6	Started pumping into well 6 at 10:45 a.m.. Finished pumping entire load into well 6 at 12:10 p.m.
6/28	p.m.	4	6, 7, & 8	Started pumping into well 6 at 3:15 p.m.. After 15 min, pressure was > 75 psi. Moved to well 7 and at 4:20 p.m. grout began to flow out of the top of well 8. Pressure in well 7 was ~ 50 psi. Returned to well 6 and started pumping. At 4:50 p.m. started pumping into well 8. At 5:00 p.m. stopped pumping into well 8 (pressure > 50 psi). Wasted 1.7 yd ³ to waste basin
6/29	a.m.	5	10 & 11	Started pumping into well 11 at 9:37 a.m.. Pumped 5-10 min and got breakthrough at ground surface. Connected to well 10 and pumped ~ 5 min. Pressure built up to 70 psi and then stopped grouting. Estimated 2 yd ² pumped (wasted remainder of load to waste basin)

Table 15. Operational description of grouting trench 151

Date	Time	Truck	Well	Comments
7/9	a.m.	6	1, 3, & 4	Checked bottom of well 8 for grout from filling of trench 170. No sign of grout; thus, no evidence of grout movement from trench 170 to trench 151. Started pumping into well 1 at 10:00 a.m.. At 10:30 a.m., started pumping into well 3 (could not pump into well 2 because of broken well cap). At 11:00 a.m., detected grout at bottom of well 2. At noon, started pumping into well 4. Finished load into well 4
7/10	a.m.	7	2, 4, & 5	At 9 a.m., well 5 had ~3 ft of grout at bottom of well (from well 4). Well 6 did not contain grout at bottom of well. At 9:47 a.m., started pumping load 7 into well 2 (well cap repaired for pumping). At 10:16 a.m., well 5 had ~5 ft of grout on bottom of trench. However, well 6 did not have grout at bottom. At 10:22 a.m., pressure at well 2 was >50 psi; thus, moved to well 4. Pressure immediately went to >60 psi (possibly plugged from yesterday's grouting!). Moved to well 5 and finished load
7/10	p.m.	8	5	Started pumping into well 5 at 1:05 p.m. At 1:32 p.m. pressure at well 5 was <5 psi. Pumped entire load into well 5. At 1:12 p.m. there was no grout at bottom of well 6, but well 7 had ~1.5 ft. At 1:27 p.m. wells 8 and 9 had 1.5 and 0.5 ft of grout, respectively. However, no grout was observed in bottom of well 10 at this time
7/11	a.m.	9	5 & 6	Started pumping into well 5 at 9:22 a.m. At 9:42 a.m., pressure at well 5 > 50 psi and then moved to well 6. At 10:29 p.m., completed load 9 (pressure at well 6 was still <10 psi)
7/11	p.m.	10	6 & 7	Started pumping into well 6 at 1:42 p.m. Moved to well 7 at 2:25 p.m.. Load emptied at 2:42 p.m. (pressure at well 7 was 5-10 psi)
7/12	a.m.	11	7, 8, & 9	Started pumping into well 7 at 9:56 a.m.. At 10:12 a.m., grout broke through the ground surface ~5 ft north of well. Moved to well 8 (10:15 a.m.) and pumped until 10:58 a.m. when grout started coming up around well 8's casing. Pumped remainder of load into well 9
7/12	p.m.	12	9 & 10	At 1:35 p.m., started pumping into well 9. At 1:42 p.m., grout broke through the ground surface. Moved to well 10 where pumping was continued for 5 min. after which more grout came to the surface. A one to two sq yard area of soil was lifted until it cracked releasing grout to the surface. About 2 yd ³ was injected, the remainder of load 12 was pumped to the waste basin

disposed of in the trench, which is quite variable from trench to trench within SWSA 6.

3.5 GROUNDWATER MONITORING RESULTS

Sampling of groundwater was very limited because of the site's elevated position above groundwater. The only wells found to contain water were wells 165-NW and 165-SW; however, a routine monitoring program (i.e., weekly or monthly sampling) was not instigated. Tamura et al. (1987) observed that ^{90}Sr concentrations in trench leachate sampled from trench 150 decreased significantly (from $>20,000$ to <100 Bq/L) after grouting with the same cement-based grout. The pH of trench leachate was increased from values <7 to values >9.5 , presumably because of the elevated levels of sodium. No pregrouting levels of sodium were available for trench 150 leachate. However, concentrations of sodium in trench leachate of the adjacent trench (trench 152) were <5 mg/L compared with sodium concentrations ranging from 50 to 130 mg/L in leachate sampled from trench 150 after grouting. These results strongly imply that sodium concentrations were greatly increased by grouting with a cement-based grout. Concentrations of calcium and magnesium in leachate from trench 150 after grouting were also much lower than concentrations in leachate from an ungrouted adjacent trench. This suggests that as sodium concentrations rose, calcium and magnesium concentrations were lowered by grouting with a cement-based grout.

Water sampled from 165-NW and 165-SW wells outside the trench area contained higher levels of radioactivity (gross-alpha, gross-beta, and ^{90}Sr) after grouting (sampled in February 1991) compared with before grouting (sampled in June 1990). The greatest difference was in the concentrations of gross-beta activity, levels between 1 and 2 Bq/L before grouting as compared with 7 and 10 after grouting (Table 16). Strontium-90

Table 16. Radioactivity in water sampled from wells 165-NW and 165-SW before and after grouting

Radioactivity (Bq/L)	Before Grouting		After Grouting	
	Well 165-NW	Well 165-SW	Well 165-NW	Well 165-SW
Gross alpha	0.27	0.10	0.23	0.20
Gross beta	1.1	1.7	9.6	7.0
^{90}Sr	0.63	0.62	1.2	1.3

concentrations were also higher in water sampled after grouting, but levels of gross alpha remained unchanged. If the character of groundwater were to be significantly changed as a result of grouting with a cement-based grout, levels of sodium would be expected to be elevated as the bleed water or leachate from the alkali-based grout came in contact with the groundwater. However, concentrations of sodium in water sampled from these wells after grouting were similar to those found in water before grouting (Table 17). Also, unlike ^{90}Sr concentrations, the levels of Ca, Mg, and Sr were similar in water sampled before versus after grouting. The major difference in water quality before versus after grouting appears to be in levels of Al, Fe, Ni, and Zn. Concentrations of all of these metals were elevated in water sampled after grouting. Elevated concentrations of these metals are probably the result of increased reducing conditions in the groundwater during February (cool and wet) compared with conditions in the groundwater during June rather than any influence of grouting per se.

Table 17. Concentrations of metals (mg/L) in water

	Before Grouting		After Grouting	
	Well 165-NW	Well 165-SW	Well 165-NW	Well 165-SW
Ag	<0.005	<0.005	<0.005	<0.005
Al	0.46	<0.05	9	6.1
As	<0.05	<0.05	<0.05	<0.05
B	<0.08	<0.08	<0.08	<0.08
Be	<0.0002	<0.0002	0.0019	0.001
Ca	85	46	83	41
Cd	<0.005	<0.005	<0.005	<0.005
Co	<0.004	<0.004	0.036	0.057
Cr	0.007	0.005	0.025	0.019
Cu	0.009	<0.005	0.022	0.017
Fe	0.49	0.089	29	12
Li	<15	<15	<15	<15
Mg	15	9.2	26	12
Mn	0.097	2.2	1	1.3
Mo	<0.04	<0.04	<0.04	<0.04
Na	13	14	10	19
Ni	0.005	<0.005	0.017	0.021
P	<0.3	<0.3	0.8	0.64
Pb	<0.05	<0.05	0.44	<0.05
Sb	<0.05	<0.05	<0.05	<0.05
Se	<0.05	<0.05	<0.05	<0.05
Si	13	8.8	14	20
Sn	<0.05	<0.05	0.051	<0.05
Sr	0.2	0.089	0.22	0.091
Ti	<0.02	<0.02	<0.02	<0.02
V	<0.002	<0.002	0.028	0.014
Zn	0.019	0.006	0.15	0.21
Zr	<0.02	<0.02	<0.02	<0.02

4. SUMMARY, CONCLUSIONS, AND NEEDS

A technology being evaluated for use in the closure of one of the low-level radwaste burial grounds at ORNL is trench stabilization using a cement-based grout. To demonstrate the applicability and effectiveness of this technology, two interconnecting trenches in SWSA 6 were selected as candidates for in situ grouting with a particulate grout. The trenches are ~15 ft deep and measure 42 x 14 ft and 44 x 14 ft. The primary objective was to demonstrate the increased trench stability (characterized by trench penetration tests) and the decreased potential for leachate migration (characterized by hydraulic conductivity tests) following in situ injection of a particulate grout into the waste trenches. Stability against trench subsidence is a critical issue. For example, construction of impermeable covers to seal the trenches will be ineffectual unless subsequent trench subsidence is permanently suspended.

A grout composed of 39% Type 1 Portland cement, 55.5% Class F fly ash, and 5.5% bentonite mixed at 12.5 lb/gal of water was selected after laboratory testing of several grout formulations. Results of laboratory studies revealed that this formulation exhibited no liquid-to-solid phase separation and a compressive strength of >900 psi after 28 d. Penetration resistance after 2 d was >8000 psi. Most important, the viscosity of the freshly made grout was <50 cP, allowing it to penetrate and fill intermediate-size trench voids, and the suspension was stable for pumping and injection for up to 8 h.

Before the trenches were grouted, the primary characteristics relating to physical stability, hydraulic conductivity, and void volume of the trenches were determined. Their physical stability was evaluated using soil-penetration tests. Pregrout soil-penetration tests revealed that at depths >5 and <15 ft, blows per foot within the trench averaged approximately ten fewer than those outside the trench. These data imply that considerable uncompacted soil and/or void space exists within the trench area which over time will lead to significant subsidence of the upper soil layers. Hydraulic conductivity tests within the trench area also revealed a high potential for the infiltration of water (hydraulic conductivities >0.1 cm/s).

Void volume within the trenches was determined by two techniques: (1) water-pump tests and (2) a newly developed air-pressurization technique. Estimates of void volume using the air-pressurization technique were ~100% higher than that determined by the water-pump test (230 yd³ compared with 115 yd³). It is not clear which of the two techniques is the most accurate because each has theoretical and operational constraints. Void volume estimates from the water-pump test likely represent the void volume available for grouting more than estimates by the air-pressurization technique. The development of the air-pressurization technique was pursued because the water-pump test could result in serious leaching of radionuclides and/or hazardous wastes into groundwater and may induce premature settling of soil overburden into the trench. The water-pump test also leaves soil within the trench near saturation levels for a

significant time, which could have an influence on solidification of grout introduced into the trench. Consequently, flooding trenches with water is no longer an acceptable practice for determining trench void volume. The air-pressurization method is fast and can be repeated under a variety of pressures and airflows. It is environmentally superior to the water-pump test in that it does not promote the leaching of contaminants to groundwater. The major concern in the use of the air-pressurization technique is that its accuracy has not been validated. More research is needed to demonstrate its accuracy, precision, and its theoretical and operating limitations under controlled conditions .

Soil-penetration tests revealed considerable uncompacted soil or void space within the trench area. For example, at depths >5 and <15 ft, blows per foot within the trench averaged ~ 10 blows fewer than those outside the trench. After grouting, soil-penetration tests disclosed that stability had been improved greatly. For example, refusal (defined as >100 blows to penetrate one foot) was encountered in 17 of the 22 tests conducted within the trench area. Mean refusal depths for trenches 151 and 170 were 10.4 and 8.5 ft, respectively. The postgrouting soil-penetration tests revealed that the stability of the trench after grouting was significantly better than before groutings, and at depths >8 ft, the stability (as measured in terms of soil-penetration) was very near that observed in the native soil formation outside the trench.

Pregrouting tests ranged from 10 to 20 mean blows per foot whereas postgrouting tests ranged from 20 to 40 mean blows per foot. The major differences in results between postgrouting tests and tests conducted in native soil formations outside the trench were found at soil depths of 6, 7, and 8 ft. Tests within the trench showed lower stability within this range (5 to 8 ft), probably because of the presence of intermediate-size soil voids (formed during backfilling) that were too small to be penetrated and filled by the conventional cement grout formulation.

Hydraulic conductivity within the trench remained very high (>0.1 cm/s) and significantly greater than that outside the trench. Postgrouting air-pressurization tests also revealed a large degree of intervoid linkage within and between the two trenches. Even after grouting, the combined void volume of the two trenches by this test procedure was 80 yd^3 (compared with 230 yd^3 for the ungrouted trenches). Only 79 yd^3 of grout were injected leaving 71 yd^3 unaccounted for [i.e., total void volume measured (230 yd^3) minus the sum of the grout injected (79 yd^3) plus the void volume measured after grouting (80 yd^3)]. Thus, it appears that to effectively reduce hydraulic conductivity and to develop stability within the upper level of the trench, it may be necessary to implement additional stabilization steps. One possibility is the injection of a chemical or microfine cement grout into the upper level of the grouted trench which may fill voids too small for the conventional grout.

Grouting of trenches with conventional particulate grouts typically fill only 30 to 60% of the available void volume, allowing the trenches to remain vulnerable to a certain degree of leaching. On the other hand, chemical grouts typically fill all of the void

volume but generally tend to be considerably more costly. Certain chemical grouting materials (e.g., acrylamide) are also toxic and present a risk to those who prepare and inject it and are potential contaminants to drinking water supplies. For these reasons, considerable testing is required to demonstrate that the chemical's use will not present unacceptable risks. Recently, microfine-size cements have become readily available. These cements, most often made from finely ground blast-furnace slag, can be used to form slurries capable of attaining permeabilities on the order of 10^{-5} to 10^{-9} cm/s when injected into fine sands. These highly permeable microfine grout formulations are attractive from the standpoint of being superior to conventional Portland cement grouts in providing hydrologic isolation. However, their costs are approximately ten times that of conventional Portland cements, and in certain instances, their costs are similar to those of chemical grouts.

Recent experience with some microfine cement indicated that low ratios (1:1) of water to cement would have to be used unless special equipment was purchased to suspend suspensions containing high (3:1) water:cement ratios (Table 18). For example, formulations based on high (3:1) water:cement ratios would require high-energy mixers (those that generate sufficient shear to fully disperse the microfine cement) to avoid significant liquid/solid phase separation. An alternative grout formulation was investigated by using blends of bentonite clay and microfine cement with varying ratios of water. One formulation that was found to be stable and pumpable through a 12-in. column of coarse sand was made using an 8:1:1 ratio of water, bentonite, and microfine cement. Relative to cost, the formulation was much less expensive than chemical grouts or microfine cement grouts formulated on a 1:1 basis. Because of its higher permeability, such a formulation will offer significantly better hydrologic isolation of waste trenches than conventional particulate grouts. Perhaps the best approach is to use a combination of conventional particulate grout to fill the large void spaces, often present at the bottom of the trench, and a microfine grout to fill the intermediate and small void spaces in the upper levels of the trench. This would be economical and technically feasible.

To demonstrate the utility of this approach, it is proposed to inject a clay/microfine cement grout into the upper sections of trenches 151 and 170. The formulation will be mixed and pumped by the grout module (Fig. 6) into the trenches using the injection wells developed from the postgrout soil-penetration tests (Fig. 19). Slotted pipe (in wells P-3, P-7, P-11, P-15, P-18, and P-20, and P-24) used for the postgrouting air-pressurization tests have been replaced with solid nonslotted pipe. After injection of the clay/microfine cement grout through the remaining slotted injection wells, the solid pipes will be removed and the holes used to determine hydraulic conductivity. Additional soil-penetration tests will also be conducted to examine if the stability in the 5- to 8-ft depths has improved as a consequence of grouting with the clay/microfine cement grout.

Table 18. Estimated material costs for various grouting scenarios

Type of grout	Formulation	Estimated costs	
		yd ³	Trench
conventional particulate grout ^a	0.7:1 Water:dry blend	\$42	\$2,180 ^b
Microfine (MF) cement grout	1:1 Water:MF cement	\$550	\$35,750 ^c
Microfine (MF) cement grout	3:1 Water:MF Cement	\$260	\$16,830 ^c
Clay & MF cement grout	8:2:1 Water:bentonite:MF cement	\$160	\$10,100 ^c
Polyacrylamide	Chemical	\$650	\$42,300 ^c

^aGrouting formulation used in SWSA-6 trenches 151 and 170 in 1990.

^bAssumes 65 yd³ void space in trench and 60% of void volume is filled with grout.

^cAssumes 65 yd³ void space in trench and 100% of void volume is filled with grout.

5. FOLLOW-UP STUDIES
GROUTING WITH CLAY-MICROFINE-CEMENT (CMFC) GROUTS

Grouting trenches 170 and 151 with a particulate-based grout made from Portland Type I cement, fly ash, and bentonite appeared to make a significant improvement in trench stability; thus, the procedure provides assurance against trench subsidence after capping for final closure of the SWSA 6. However, measurements conducted after grouting indicated that hydraulic conductivity within the trench area remained much greater than hydraulic conductivity of the natural soil formation outside the trench. If the hydraulic conductivity within the trench area is to be significantly decreased, a grout formulation capable of entering and permeating the small void spaces within the trench is necessary. Spalding et al. (1989) demonstrated that polyacrylamide-based chemical grouts were capable of reducing hydraulic conductivities within SWSA 6 burial trenches to values as low as 7.9×10^{-7} cm/s (as compared with values of 4.0×10^{-4} cm/s for natural soil formations). One alternative to chemical based grouts is a particulate-based grout prepared from very fine grained cement (Zebovitz et al. 1989; Krizek and Helal 1989). These microfine cements have grain-size distributions (50% by weight) of < 5

Table 19. Properties and composition of microfine cements

	MC-100	MC-500
Properties		
Cementitious material	Slag	Slag/Portland
Fineness (cm ² /g)	13,000	9,000
Specific gravity (g/cm ³)	3.0	3.0
Composition (wt%)		
SiO ₂	35.4	30.6
Al ₂ O ₃	16.0	12.4
Fe ₂ O ₃	0.3	1.1
CaO	43.3	48.4
MgO	3.5	5.8
SO ₃	0.3	0.8
Total	98.8	99.1

μm as compared with $<20 \mu\text{m}$ for Type I Portland cements.

The principal manufacturer of these microfine cements is the Onoda Cement Corporation of Japan, and Geochemical Corporation presently markets them in the United States under the names of MC-500 and MC-100 (see Table 19, data taken from Krizek and Helal, 1989). The major difference between the two microfine cements is that the MC-500 contains significant quantities of Portland cement and does not require the use of sodium hydroxide as an activator for the cementitious-hydration process. Limited information is available about their preparation and performance. The manufacturer recommends shear mixing at water-to-cement ratios of 1:1 to 3:1. At low water-to-cement ratios, the bleeding rate (sedimentation rate following mixing) is small (at 1:1 water-to-cement ratios usually $<10\%$ of the initial volume), but as the ratio of water-to-cement is increased to 3:1, the bleeding rate can be as high as 50%. The amount and rate of bleeding generally decrease with increases in shear mixing time. This may be because of the increased temperature generated on shear mixing which in turn accelerates the hydration process, resulting in a shorter set time and less time available for sedimentation. The MC-100 is less affected by mixing time than MC-500 because the set time of the MC-100 formulations is more dependent on the amount of sodium hydroxide used as an activator. The intensity of bleeding can be reduced at higher water-to-cement ratios (2:1 and 3:1) by adding bentonite or silica fume.

One of the major advantages of using the higher water-to-cement ratios is the reduced material costs for the microfine cement. For example, material costs for grouting with a 1:1 water-to-cement ratio of microfine cement are nearly that for polyacrylamide chemical grouting (see Table 18). However, with respect to material costs (and reduced bleeding rates), grout formulations using microfine cements in combination with bentonite clays may be an attractive alternative. To investigate their potential use for grouting SWSA 6 burial trenches, treatability studies were initiated for the formulation and testing of CMFC grouts.

5.1 CMFC FORMULATION STUDIES

The intent of the initial studies was to form stable suspensions of bentonite clay using sodium hydroxide and sodium hexametaphosphate as dispersants to which quantities of microfine cement (MC-100) were added. Delta gluconolactone (a set retarder and dispersant) was also added in varying amounts (0.06 to 0.6 g/L) to test its influence on fluidity and set time (pumpability over time). The primary performance criterion involved the pumpability of the freshly made grout upward through 12 in. of coarse-textured sand (contained in a 2 in. diam column). Approximately 30 tests were conducted covering ranges in water-to-cement ratios of 1 to 16, clay-to-cement ratios of 0.5 to 2, sodium hydroxide concentrations ranging from 2.8 to 28 g/L, sodium hexametaphosphate ranging from 3 to 37 g/L, and concentrations of delta gluconolactone ranging from 62 to 621 mg/L. These tests were carried out by first preparing solutions containing the sodium hydroxide, sodium hexametaphosphate, and delta gluconolactone. Clay suspensions were

prepared by adding 100 to 200 g of clay to 700 to 800 mL of these solutions in a bench-scale laboratory Waring Blender. Clay additions were made in three approximately equal quantities and blended on low speed (18,500 rpm) for ~20 s. To these clay suspensions, 100 g of MC-100 were then blended to make the grout formulations. On the basis of these preliminary studies, formulations containing 100 g of bentonite and 100 g of MC-100 cement in 750 mL of water containing on the order of 13.2 g/L of sodium hydroxide, 200 mg/L of delta gluconolactone, and 20 g/L of hexametaphosphate were the ones most easily pumped to within 1 in. of the top of a 12-in. column of sand. Low concentrations of sodium hydroxide or sodium hexametaphosphate resulted in highly viscous solutions that could not be pumped through the coarse textured sand.

To define more precisely the influence of sodium hydroxide, sodium hexametaphosphate, and delta gluconolactone on the fluidity of CMFC grouts, a 3x3x3 factorial-designed experiment was conducted. Three levels of sodium hydroxide (4.2, 18.3, and 41.6 g/L), sodium hexametaphosphate (0.28, 2.81, and 28.1 g/L), and delta gluconolactone (0, 0.17, and 0.42 g/L) were used. Grout samples were prepared using 100 g of bentonite and 100 g of MC-100 in 800 mL aliquots of the appropriate levels of sodium hydroxide, sodium hexametaphosphate, and delta gluconolactone as described above. Fluidity was evaluated by recording the consistency as measured by a Bostwick consistometer (the distance in cm the grout flowed under its own weight; 24 cm was the maximum reading) at 30-min intervals over a 2 h period in which the grout was continuously stirred in a rotary drum mixer at rate of ~30 rpm. The 2 h interval was chosen because this was the estimated time required to pump 400 gal of the CMFC grout into a trench using the grouting module and pump (see Fig. 9). Fluidity of the grout mixtures was strongly influenced by the concentrations of sodium hydroxide and hexametaphosphate. Gluconolactone concentrations appeared to have little influence on fluidity after 2 h of mixing. Statistical analyses [using the GLM procedure of SAS (1985) and assuming no interactions among the three variables] revealed that increasing levels of sodium hydroxide and hexametaphosphate significantly increased the fluidity of grout (Table 20).

Grout formulations whose fluidity was > 15 cm after 2 h of mixing were poured into small plastic cups (~35 mL) and aged one week in a +90% relative humidity chamber to evaluate their setting characteristics (Table 21). Penetrability of the solidified grout forms was determined using a handheld penetrometer. Sodium hexametaphosphate at 28 g/L appeared to prevent setting (Table 21). The most promising formulations based on these tests appeared to be those containing 41.6 g/L of sodium hydroxide and 2.81 g/L of sodium hexametaphosphate (i.e. all formulations showed a fluidity of > 24 cm and a penetrability of > 4.5 kg/cm³). Additions of gluconolactone (up to 0.42 g/L) did not appear to influence fluidity or penetrability of grout formulated at these concentrations of sodium hydroxide and sodium hexametaphosphate (Table 21). To test the influence of additional loading of bentonite on fluidity, a formulation based on 41.6 g/L of sodium hydroxide, 2.81 g/L of sodium hexametaphosphate, and 0.17 g/L of

gluconolactone was mixed with 200 g of bentonite and 100 g of MC-100 (rather than the 100 g of bentonite and 100 g of MC-100). Fluidity of this formulation (using the Bostwick consistometer) after 2 h mixing remained quite high (19 cm) which indicated that loading rates of bentonite to MC-100 could be increased to a 2:1 ratio. To test the compressive strength of this formulation, freshly prepared grout was poured into 2-in.-cube molds (see Sect. 2.7.2) and cured for 43 d in a +90% relative humidity chamber. The average compressive strength measurement from three blocks was 66.3 ± 11.6 psi.

5.2 LEACHING STUDIES

The primary purpose in conducting the leaching studies was to determine if additions of sodium hexametaphosphate to grouting formulations adversely affected the leaching rates of radionuclides, notably strontium, from grout forms. Hexametaphosphate is a condensed cyclic polyphosphate that is known to form soluble complexes with many metals and is widely used in industry as a water softener ("Calgon"). Thus, it was important to evaluate hexametaphosphate's effect on the leaching characteristics of grout formulations. Obviously, injection of a grout containing hexametaphosphate into trenches could result in adverse consequences if hexametaphosphate tended to complex and mobilize radionuclides into soluble forms.

Table 20. Fluidity of grout as influenced by chemicals added¹

Chemical added	Level (g/L)	Fluidity (cm)
Sodium hydroxide	4.2	0.4 ^c
	18.3	11.8 ^b
	41.6	23.3 ^a
Sodium hexametaphosphate	0.28	9.5 ^b
	2.8	9.8 ^b
	28.0	16.1 ^a
Gluconolactone	0	10.6 ^a
	0.17	10.7 ^a
	0.42	14.1 ^a

¹Fluidity values for a specific chemical with different superscripts are significantly different at the 5% level.

Table 21. Fluidity and penetrability of grouts

Fluidity	Sodium metaphosphate	Sodium hydroxide	Gluconolactone	Penetrability
(cm)		(g/L)		(kg/cm ²)
0.0	0.28	4.2	0	ND ¹
0.0	0.28	4.2	0.17	ND
0.0	0.28	4.2	0.42	ND
0.0	2.81	4.2	0	ND
0.0	2.81	4.2	0.17	ND
0.0	28.09	4.2	0	ND
0.0	28.09	4.2	0.17	ND
0.0	0.28	18.3	0	ND
0.3	2.81	18.3	0	ND
1.0	28.09	4.2	0.42	ND
2.3	0.28	18.3	0.17	ND
2.5	2.81	4.2	0.42	ND
4.3	2.81	18.3	0.17	ND
9.5	2.81	18.3	0.42	ND
17.8	0.28	41.6	0.17	3.5
18.0	0.28	18.3	0.42	<2.5
24.0	28.09	18.3	0	NS ²
24.0	28.09	18.3	0.17	NS
24.0	28.09	18.3	0.42	NS
24.0	0.28	41.6	0	3.0
24.0	0.28	41.6	0.42	4.5
24.0	2.81	41.6	0	>4.5
24.0	2.81	41.6	0.17	>4.5
24.0	2.81	41.6	0.42	>4.5
24.0	28.09	41.6	0	NS
24.0	28.09	41.6	0.17	NS
24.0	28.09	41.6	0.42	NS

¹ND = not determined²NS = nonsetting

The leaching characteristics of radio-strontium, -cesium, -cobalt, and tritium from three grout formulations were compared using the ANS-16.1 leaching test (ANSI/ANS 1986). The methods to make the three grout formulations are described in Table 22. Activities of ^{85}Sr , ^{57}Co , ^{134}Cs , and tritium (HTO) were mixed into aliquots of each formulation, which were then poured into 1.5-cm-diam and 4.2-cm-high cylindrical forms. After setting for 2 d the solidified grout was removed from the forms and submerged into demineralized distilled water as prescribed in the ANS-16.1 protocol. Two replicates of each formulation were leached. Fresh demineralized water was exchanged at 2, 7, 24, 48, 72, 96, and 120 h and at 18, 46, and 91 d. Activities of the gamma emitting radionuclides were determined in the leach solution (and compared with activities added to the solidified forms in the same counting geometry) using a high-resolution, solid-state, coaxial, lithium-drifted, germanium [Ge(Li)] detector coupled to a ND6700 multichannel analyzer with 4096 channels. Tritium (HTO) levels in the leach solutions were determined by liquid scintillation counting after correcting for counting efficiencies of selected aliquots whose tritium levels were determined by EPA Method 906.0. Replicate leachates were not analyzed for tritium (i.e., single replicates), and only those leachates collected the first 120 h were analyzed.

The leachability index (L) defined by the ANS-16.1 procedure is the negative log of the effective diffusivity (D) of a nuclide from a test material; i.e.,

$$L = \log\left(\frac{\beta}{D}\right)$$

where β is a defined constant of $1.0 \text{ cm}^2/\text{s}$, and D is expressed in units of cm^2/s , making L a dimensionless parameter. The effective diffusivity (D) is determined experimentally over ten discrete time intervals ranging from 2 to 1032 h over 90 d (for more information about the test, see ANSI/ANS-16.1 1986). The full-scale test involves expressing the leaching index as an average of the required ten leaching intervals (up to 90 d). These values were determined for ^{57}Co , ^{134}Cs , and ^{85}Sr . However, for tritium leaching an abbreviated test (up to 120 h, using the average of 7 rather than 10 leaching intervals) was conducted.

Leachability indexes for ^{57}Co , ^{134}Cs , ^{85}Sr , and HTO from the three grout formulations are presented in Table 23. The cobalt radioisotope was very slowly leached from all three formulations (leachability indexes of ~ 12). The major differences in the leaching characteristics of the three formulations were the much lower leaching indexes (i.e., higher leaching rates) for ^{134}Cs and ^{85}Sr with the Portland cement-based grout as compared with those of the microfine- or CMFC-based grout. The lower leaching indexes for these radionuclides imply that the leaching of these radionuclides is on the order of ~ 1000 times faster from Portland cement-based grout than those made from microfine cement. The "abbreviated" leachability index (taken over the first 120 h, $n=7$)

Table 22. Description of grouting formulations

Formulation	Method of Formulation
CMFC	200 g of bentonite and 100 g of MC-100 in 800 mL mixed into a solution containing 41.6 g/L of sodium hydroxide, 2.81 g/L of sodium hexametaphosphate, and 0.17 g/L of gluconolactone with a Waring Blender
Microfine cement	673 g of MC-100 mixed with 700 mL of water, 50 mL of 50% sodium hydroxide, and 5.5 mL of Ca-600 (a commercial dispersant marketed by Geochemical Corporation, Ridgewood, New Jersey) with a Waring Blender
Conventional grout formula (used in trenches 151 and 170)	585 g of Portland Type I cement, 825 g of ASTM Class F fly ash, and 82 g of bentonite mixed with 1000 mL of water in a table top rotary mixer

for tritium did not appear to vary so much between the different grout formulations. However, closer evaluation of the data reveals that the leaching index (using Eq. 1 of ANS 1986) for tritium was highly dependent on time (Fig. 24). For example, the leaching index for HTO from the microfine MC-100-based grout ranged from <6 at 2 h to near 11 after 100 h of leaching. Leaching of HTO from the Portland cement-based grout showed a similar trend. In contrast, the leaching of HTO from the CMFC-based grout was very uniform over time. In terms of quantity of HTO leached from each of the grouts, ~100% of the HTO had leached from both Portland- and microfine MC-100-based grouts after ~30 h, whereas >80% of the HTO remained with the CMFC-based grout after 120 h of leaching (see Fig. 25). These data clearly show that the CMFC-based grout would be clearly superior to those made solely from Portland or microfine cements in reducing the leaching of any of these radionuclides from the grouted form.

The cementitious setting action of microfine cements is activated by adding caustic to the formulation. In contrast, Portland-based cements contain sufficient quantities of exchangeable calcium to activate the cementitious reaction; thus, additions of caustic are not needed. Of some environmental concern is the resulting caustic effect of




Fig. 24. Leachability index of tritium as a function of time.

Table 23. Leachability indexes measured for three grout formulations

Formulation	^{57}Co	^{134}Cs	^{85}Sr	HTO
Portland (Type 1)				
1	13.1 ± 0.5	6.3 ± 0.5	7.1 ± 0.4	5.33 ± 0.05
2	12.0 ± 0.7	6.3 ± 0.5	7.0 ± 0.4	
Microfine MC-100				
1	12.1 ± 1.1	9.1 ± 0.8	10.3 ± 0.6	5.69 ± 0.05
2	11.3 ± 0.7	9.1 ± 0.7	10.3 ± 0.7	
Clay-microfine				
1	12.8 ± 1.1	9.7 ± 0.7	10.5 ± 0.6	8.9 ± 0.2
2	12.5 ± 1.1	9.7 ± 0.7	10.5 ± 0.7	

from the use of microfine cements that depend on caustic additions to initiate their cementitious reaction. For this reason, the pH of the leachates generated during the ANS-16.1 test was monitored. Generally speaking, the pH values measured on leachate generated from the Portland cement-based grouts were higher throughout the 90 d leach period than those leachates generated from the microfine cement-based grouts (see Fig. 26). During the early stages of leaching (<20 d), the pH of leachates from the CMFC grout was generally from 0.5 to 1.0 pH unit below that of the grout prepared from the Portland Type I cement. After 90 d, the pH of both leachates ranged between 10.5 and 11.0 (see Fig. 26). Thus, these data indicate that the use of microfine cements that require caustic to activate them probably do not elevate the pH of the surrounding media any more than grouts made from Portland Type I cement.

5.3 TRENCH GROUTING WITH A CMFC BASED-GROUT

Wells formed from postgrout soil-penetration tests were used to inject the CMFC-based grout into trenches 170 and 151 (Fig. 19). Injection wells were similar to those in the Phase I studies (those where a Portland Type I cement-based grout was injected in trenches 151 and 170 in the summer of 1990), with two exceptions. One, the

PVC piping (Schedule 80, 1.25-in. ID diam.) used for injection of CMFC was constructed of 0.02-in.-wide slots rather than the 0.1-in.-wide slotted pipe used in Phase I. Laboratory and field tests demonstrated that CMFC could easily be pumped through this type of pipe. For example, field tests revealed that the grout could be pumped at rates in excess of 20 gal/min with pressure drops < 10 psi at the grouting




Fig. 25. Fraction of tritium leached from selected grout formulations as a function of time.

unit. The second difference was in the manner in which the pipe/soil interface at the surface was treated. In Phase I studies, to ensure that injected grout did not return to the surface along the pipe/soil interphase, a 1-ft section of 2-in.-diam pipe was placed around the 1.25-in.-diam injection pipe and driven into the ground to ~ 3 in. below the soil surface. On being driven into the ground, soil was forced between the two pipes forming a tight seal at the pipe/soil interphase. A cement-based grout collar was then molded around the surface of the pipe/soil interphase (see Fig. 4). In this study, a 1-ft section of 2-in.-diam pipe was not placed around the injection pipe and driven into the ground as was done in the Phase I study, the rationale being that such a procedure was not needed because of the high fluidity of CMFC. However, the same type of a




Fig. 26. The pH of leachate generated from three grout formulations during the ANS-16.1 leaching test.

cement-based grout collar was installed around each of the wells.

5.3.1 Preparation of CMFC at the Field Site

In the laboratory, bentonite clay suspensions (25% by weight) were made using a high shear laboratory blender. For field studies, a cyclonic-action-type blender was used (Sidewinder Mixer™, Model SW-100 manufactured by Swaco Geolograph, Oklahoma City, Oklahoma). This type of blender is routinely used to prepare drilling muds in the oil drilling industry. To do this, 150 lb of flaked grade caustic soda, 10 lb of sodium hexametaphosphate (Calgon, powdered grade), and 0.6 lb of delta gluconolactone were blended with 400 gal of water in one of the 500-gal tanks of the grouting unit. This solution was circulated through the cyclonic blender, while 800 lb of cement-grade bentonite clay (Big Horn™ Chemical Grade, 80% passing a 200 mesh screen purchased from Wyo-Ben, Inc., Billings, Montana) were added in 50-lb increments. MC-100 was then blended (444 lb in ten 44.4 lb increments) with the clay suspension using the "lighting type" mixers mounted on the 500-gal tanks of the grouting unit. Preparation of the clay suspension and addition of the microfine cement were carried out by personnel wearing full face-masked respirators and chemical splash jackets (Fig. 27).

5.3.2 Trench Injection of CMFC

CMFC was injected into the trenches by pumping the grout from the 500-gal holding tanks using the grouting unit pumps at operating pressures <50 psi. A description of these injections is presented in Table 24. Approximately 4 yd³ of grout was injected into trenches 170 and 151. The total quantity injected was severely limited because of continued leaking of grout to the soil surface at the pipe/soil interface of the injection wells. Except for well P-17, grout broke through at the base of all wells after pumping 3 to 4 min. Pumping rates (10 to 20 gal/min at grouting pressures <25 psi) exceeded the hydraulic capacity of soil, thus causing grout to be forced upward along the injection pipe and breaking through to the soil surface around the cement-based collar installed to prevent the bleeding of grout back to the soil surface. In the Phase I studies, to ensure that injected grout did not return to the surface along the pipe/soil interphase, a 1-ft section of 2-in.-diam pipe was placed around the 1.25-in.-diam injection pipe and driven into the ground to ~3 in. below the soil surface. The same procedure should have been used for these studies even though the fluidity of CMFC approached that of water. Estimates of hydraulic conductivity within the trenches after Phase I grouting were in excess of 0.1 cm/s [i.e., 6 L of water could be poured into the wells formed from soil-penetration tests over a 23-s interval without overflowing the well casing (a flow rate of ~4 gal/min)]. However, grout injection rates were ~10 to 20 gal/min and resulted in considerable backflow of grout upward along the injection wells.



Fig. 27. Preparation of the grout formulation using a cyclonic mixer and grouting unit at the field site (ORNL 7096-91).

Approximately 8.1 yd³ of CMFC was pumped into well 151-SW (see Table 24). This was a well installed outside the trench 151 area to monitor groundwater. However, because of the quantity of grout that could be pumped into the well at such high flow rates (2.3 yd³ over a 20-min interval, >20 gal/min) it was apparent that the well was either in or directly linked to the adjoining trench (trench 148).

During the last week of July and first week of August, the injection wells in trenches 170 and 151 were modified (using the procedure implemented in the Phase I studies) to ensure that any additional injections of grout would not return to the soil surface along the pipe/soil interface. This involved removing the previously installed cement-based grout collar from around the injection wells and the installation of a 1-ft section of 2-in.-diam pipe around the 1.25-in.-diam injection pipe. After driving this section into the ground to ~3 in. below the soil surface, a new cement-based grout collar was then molded around the surface of the pipe/soil interphase. In addition, four injection wells (using PVC 0.1-in.-wide slotted pipe) were installed in trench 148 (Fig. 28).

Grouting of trenches 151 and 170 was resumed on August 8, 1991 (see Table 24). The total quantity of grout pumped into these two trenches on that date was 8.3 yd³. This quantity added to that injected July 22 and 23 (4 yd³) totals to slightly more than 12 yd³. Modification of the pipe/soil interphase of the injection wells eliminated the leaking of grout to the soil surface at the pipe/soil interphase. Breakthrough of grout to the soil surface was usually several feet away from the injection well. In a number of cases, grout surfaced out at the top of adjacent injection wells (see Table 24), indicating

Table 24. Field grouting notes

Date	Time	Load	Well	Comments
7/22/91	am	1	P-2, & P-5	Started pumping into P-2 at 8:05 am, stopped at 8:10 am (break through at base of well, pressure <30 psi). Moved to well P-5 and pumped until 8:19 am and pressure became >50 psi because the grout began to set up. Pumped remainder of load to waste tank (a total of approx. 0.6 yd ³ was pumped into the trench.
7/22/91	am	2	P-6, P-8, P-9, P-10, P-14, P-16 & P-17	Second load was made at 9:00 am (approx. 400 cm ³ of gluconolactone was added to prevent setting). Grout broke through at the base of all wells (except P-17) after pumping for 3 to 4 min. Remainder of load was pumped in to P-17. Total grout pumped into trench was 2.3 yd ³ .
7/23/91	am	3	P-8, P-10, P-17, P-19, P-21, P-22, P-23, P-25 151-SW	Tried with little success of injecting grout because of breakthrough of grout at the well base after 3 to 4 min of pumping (about 1.1 yd ³ pumped into trenches 151 and 170). Pumped remainder of load into well 151-SW (approx. 1.2 yd ³).
7/23/91	am	4	151-SW	Started pumping into 151-SW well at 9:25 am and finished pumping load (2.3 yd ³) at 9:45.
7/23/91	am	5	151-SW	Started pumping into 151-SW well at 10:48 and finished pumping load (2.3 yd ³) at 11:08.
7/23/91	pm	6	151-SW	Started pumping into 151-SW at 1:39 pm (total load, 2.3 yd ³ pumped into 151-SW).
8/8/91	am	7	P-3, P-7 & P-11	Started pumping into P-3 at 7:20 am (pressure approx. 25 psi) and stopped at 7:28 due to breakthrough of grout approx. 1 to 2 ft from well (the modified wells appeared to hold grout much better). Started pumping into P-7 at 7:32 am and stopped at 7:34 because grout came out of the top of well P-6 (viz, short circuiting from well P-7 to well P-6). At 7:35 am took sample for compressive strength measurements. Began pumping into P-11 at 7:38 and pumped remainder of load at 7:57. Total pumped into trench 2.3 yd ³ .
8/8/91	am	8	P-11 & P-15	At 9:26 am continued pumping into well P-11. Pressures as high as 75 psi were encountered. At 9:48 am grout broke through the soil surface (approx. 5 ft from well P-11) directly in front of the grout unit (total pumped into P-11 was 1.4 yd ³). Pumped remainder of load into P-15 (stopped 10:00 am).

Date	Time	Load	Well	Comments
8/8/91	am and pm	9	P-15 & P-18	At 11:03 am, started pumping into P-15. After pumping approx. 1.1 yd ³ , pumping was stopped when grout began to come out of the top of wells P-14 and P-16 (11:15 am). At 11:18 am, began pumping into P-18 and pumped remainder of load (11:27 am).
8/8/91	pm	10	P-18, P-24 & 148-4	Began pumping into P-18 at 1:27 pm. After approx. 5 min., grout broke out on to the general soil surface (around wells P-19, P-20 and P-21). Moved to well P-24 at 1:35 pm. Pumped until 1:45 pm when grout broke out of the soil surface around wells P-22 and P-25. Assumed trench 151 was filled and moved to trench 148 where remainder of load (approx. 0.9 yd ³) was pumped into well 148-4.
8/13/91	am	11	148-3	At 6:53 am, began pumping into well 148-3. Completed at approx. 7:20 am (2.3 yd ³).
8/13/91	am	12	148-3	Pumped entire load in to well 148-3.
8/13/91	am	13	148-3	Started 9:50 am and finished 10:06 am (max. pressure was 50 psi).
8/13/91	am	14	148-3	Started 10:13 am and finished 10:31 (max. pressure was 50 psi).
8/13/91	am	15	148-3	Started 11:01 am and finished 11:18 am (max. pressure <50 psi).
9/19/91	pm	16	148-3	Entire load (max. pressure <50 psi). Made viscosity determination.
9/19/91	pm	17	148-3	Entire load (max. pressure <50 psi).
9/19/91	pm	18	148-3	After pumping approx. 1.2 yd ³ well 148-2 had approx. 2.5 ft of grout in bottom of well and well 148-2 had grout up to approx. 3 ft of soil surface. Pumped entire load (max. pressure <50 psi).
9/19/91	pm	19	148-3	After pumping approx. 0.6 yd ³ , grout began flowing from the top of well 148-2. Capped well 148-2 and continued pumping remainder of load into well 148-3 (max. pressure <50 psi). Observed leakage of grout on soil surface around well 148-3.

Date	Time	Load	Well	Comments
9/20/91	am	20	148-3	Took samples for compressive strength tests. Pumped entire load into well 148-3. At the end of pumping, grout came to the surface around well 148-3 (did not leak at the well-soil interphase, appeared to be breaking through the soil surface at a number of places)
10/24/91	am	21	All wells in trench 148	Tried to pump into well 148-4 (plugged with grout). Moved to well PM-1 and pumped approx. 1.1 yd ³ until breakthrough at soil surface north of well 148-2. Moved to well PM-2 and observed direct link to well PM-1 and grout continued to come to the surface around well 148-2. Moved to well 148-1 and pumped approx. 0.6 yd ³ and got breakthrough at soil surface. Also pumped into well 148-3 and got breakthrough at soil surface. Total volume pumped was approx. 1.7 yd ³ .

considerable subsurface movement of grout within the trench.

Trench 148 was prepared for grouting with CMFC. This action was taken because it didn't appear that large quantities of CMFC could be injected into a trench previously grouted with a Portland Type I-based cement grout (trenches 151 and 170). Grouting trench 148 with CMFC would provide an additional data base in our trench grouting studies. For example, grouting data would be available for (1) trenches grouted with a conventional Portland Type I-based grout, (2) trenches grouted with CMFC after grouting with the conventional Portland Type I-based grout, and (3) a trench grouted solely with CMFC. Soil-penetration and hydraulic conductivity tests on these trenches before and after grouting would determine the effectiveness of the various grouting scenarios.

Trench 148 was grouted with CMFC at intermittent dates in August, September, and October of 1991 (Table 24). Ideally it may have been preferred to grout a trench in one single continuous operation (at least on a day-to-day basis); however, equipment failures and difficulties in obtaining Plant & Equipment personnel to operate the grouting unit precluded such an operation. In retrospect, grouting under these conditions demonstrated the utility of not requiring a single continuous operation. For example, grouting on a day-to-day basis allowed measurement of grout levels in injection wells, and because slotted pipe was used to inject grout, the same well could be used to inject




Fig. 28. Location of wells used to inject grout into trench 148.

grout the following day or several days later. A total of 25.7 yd³ of grout was injected into trench 148 during August through October (see Table 24). This quantity added to the 8.1 yd³ of grout injected into well 151-SW (assumed to be linked to trench 148) gives a total of 33.8 yd³ injected into trench 148. The total void volume of trench 148 was not determined; thus, any calculation of the efficiency in filling its void volume can not be made. For comparison, trenches 151 and 170 received 91 yd³ of grout (79 yd³ of conventional Portland Type I-based grout and 12 yd³ of CMFC).

5.3.3 Field Testing of CMFC Grouted Trenches

Soil-penetration and hydraulic conductivity tests were conducted within trenches 151, 170, and 148 prior to and after grouting with CMFC. Compressive strength and viscosity measurements of field grout samples were also determined. For example, the compressive strengths of three samples taken during the August 8, 1991, field injections were 34.4 ± 1.5 psi (aged 60 d in +90% relative humidity chamber), considerably lower than the 66.3 psi measured on the laboratory-generated samples (see sect. 5.1). Field viscosity measurements for CMFC were made by comparing flow rates through a specially designed funnel with flow rates of water and a 72% glycerol solution. Estimates of CMFC viscosity determined in this manner were 5 to 6 cP.

Soil-penetration tests from the Phase I studies showed a marked improvement in trench stability following grouting with the conventional Portland Type I-based cement grout (see Fig. 13 of Phase I studies). Soil-penetration tests in trenches 151 and 170 (locations illustrated in Fig. 29) after grouting with CMFC gave the indication that the stability within the trenches was less than that after grouting with Portland Type I based grout (see Fig. 30); viz, the average number of blows per foot for penetration tests after grouting with CMFC was considerably less. However, statistical analyses (using Proc GLM with Duncan's multiple-range test, SAS 1985) revealed significant differences ($P < 0.05$) only at the 1- and 7-ft depths (see Appendix B). At the 7 ft depth, the average number of blows per foot after grouting with CMFC was significantly less than the average number of blows per foot in soil outside the trench, but it was not significantly different from the average number of blows per foot following grouting with the Portland Type I-based grout, indicating that the grouting with CMFC did not significantly affect the stability of the two trenches.

Soil-penetration tests in trench 148 indicated that grouting with CMFC did not significantly affect trench stability (see Fig. 30). Statistical analyses of the soil penetration data revealed no significant differences in the average number of blows per foot before and after grouting; however, at soil depths > 5 ft they were significantly lower than the average number of blows per foot in soil outside the trench (see Appendix C). These data also indicate that grouting with CMFC did not significantly affect the stability of trenches.

Hydraulic conductivity measurements following grouting with CMFC were




Fig. 29. Locations within trenches 148, 151, and 170 where hydraulic conductivity measurements were taken.

conducted in wells formed from the soil penetration tests. In this case, 5-ft sections of 2-in.-diam PVC pipe were driven into the well to form an infiltration barrier for the top 5 ft of soil. Hydraulic conductivities of the grouted trench area surrounding each well were determined using a constant head pump-in test (Spalding et al. 1985).

Hydraulic conductivities were calculated using the following formula

$$K = \frac{q \ln \left[\frac{mL}{D} + \left(1 + \left(\frac{mL}{D} \right)^2 \right)^{1/2} \right]}{2\pi L H_z}$$

where

- K = hydraulic conductivity in cm/sec,
- q = rate of water intake in cm³/sec,
- L = length of intake section in cm,
- H_z = constant piezometric head in cm of water which equals the height of the water in the casing above the water table,
- D = diameter of well casing in cm, and
- m = transformation ratio, assumed to be 1.

Six measurements were made in trenches 151 and 170, and four were made in trench 148 (see Fig. 29 and Table 25). The average hydraulic conductivity in trenches 151 and 171 after grouting was 1.2×10^{-3} cm/s. After grouting trench 148 with CMFC, the average hydraulic conductivity was 1.7×10^{-3} cm/s. Two measurements of hydraulic conductivity in soil outside




Fig. 30. Trench 148 soil penetration tests.

and adjacent to the trenches averaged 6.4×10^{-5} cm/s indicating grouting of the trenches by either of the two methods (Portland Type I followed with CMFC or with CMFC by itself) did not result in measurements of hydraulic conductivity within the trench area equivalent to that of the natural soil.

Table 25. Measurements of hydraulic conductivity within and adjacent to the trenches

Location	Well	Hydraulic conductivity (cm/s)
Trench 170	F-1	1.1×10^{-3}
	F-2	1.1×10^{-3}
	F-3	1.5×10^{-3}
	F-4	1.1×10^{-3}
Trench 151	F-5	6.6×10^{-4}
	F-6	1.7×10^{-3}
Trench 148	F-9	2.2×10^{-3}
	F-10	7.1×10^{-4}
	F-11	1.3×10^{-3}
	F-13	2.4×10^{-3}
Outside trench area	M-1	1.1×10^{-4}
	M-2	1.8×10^{-5}

6. SUMMARY AND CONCLUSIONS

Low-level radwaste burial trenches were grouted with cement-based grouts to improve stability against long-term subsistence and to reduce hydraulic conductivity of the water into the trenches and potential transport of contaminants to groundwater. During the summer of 1990, two trenches (trenches 151 and 148) were grouted with a particulate-based grout made from Portland Type I cement, flyash, and Wyoming bentonite. Soil-penetration tests conducted before and after grouting of these trenches strongly indicated profound increases in trench stability. However, hydraulic conductivity measurements before and after grouting indicated grouting had not made a major impact in lowering the hydraulic conductivity within the trench area and some follow-up studies were recommended.

The following summer (1991), the same two trenches (trenches 151 and 170) previously grouted with the Portland Type I cement-based grout, were grouted again with another particulate-based grout made from a microfine cement (a fine grained cement >50% by weight to be <5 μ m diam) and Wyoming bentonite to fill the unfilled void spaces and reduce hydraulic conductivity within these trenches. The same clay-microfine-cement (CMFC) grout was also injected into a another trench (trench 148). The Portland Type I cement grout filled ~17 of the trench volume (trenches 151 and 170) and the CMFC grout filled ~13 of trench 148 volume (assuming trench depth of 10.4 ft).

Approximately 12 yd³ of the CMFC was injected into the previously grouted trenches 151 and 170 with the expressed purpose of lowering hydraulic conductivity within these trenches. Measurements of hydraulic conductivity within trenches 151 and 170 after grouting with the CMFC grout averaged 1.2×10^{-3} cm/s, considerably higher than average hydraulic conductivity in soil outside the trenches (6.4×10^{-5} cm/s). Thus, these data indicate grouting with the clay-microfine cement did not reduce hydraulic conductivity to levels commonly observed in surrounding soils. The average hydraulic conductivity measured in the CMFC grouted 148 trench was approximately the same as that measured in the grouted 151 and 170 trenches (1.7×10^{-3} cm/s) and much higher than the average measured in the surrounding soils, again indicating grouting with the CMFC grout did not appreciably lower hydraulic conductivity measurements in the trench. In addition, trench stability was not increased using the CMFC grout. For example, soil-penetration data from trench 148 before and after grouting with the CMFC grout revealed no significant difference ($P < 0.5$) in the number of blows to penetrate the distance of one foot indicating no benefits in increased trench stability from the CMFC grout.

These in-situ grouting studies of low-level burial trenches with cement-based grouts (using Portland Type I cement) have shown considerable benefit in increasing trench stability against potential future subsistence; however, little effect can be expected

with regard to lowering hydraulic conductivity within the trenches, even if clay-based microfine cements are used as grouting materials.

7. REFERENCES

- American Nuclear Society. 1986. American National Standard Measurement of the Leachability of Solidified Low-Level Radioactive Wastes by a Short-Term Test Procedure. ANSII/ANS-16.1 American Nuclear Society, La Grange Park, Illinois.
- Bechtel National, Inc. 1988. Closure plan for Solid Waste Storage Area 6. Vol. 1: Closure plan. ORNL/RAP/Sub-87/99053/9&V1. Oak Ridge National Laboratory.
- Davis, E. C., and B. P. Spalding. 1986. Field evaluation of a cement-bentonite grout and a chlorosulfonated polyethylene fabric liner in hydrologically isolating low-level radioactive solid waste. ORNL/TM 9742. Oak Ridge National Laboratory.
- Davis, E. C., W. J. Boegly, Jr., E. R. Rothschild, B. P. Spalding, N. D. Vaughan, C. S. Haase, D. D. Huff, S. Y. Lee, E. C. Walls, and E. D. Smith. 1984. Site characterization techniques used at a low-level waste shallow land burial field demonstration facility. ORNL/TM-9146. Oak Ridge National Laboratory.
- Krizek, R. J., and M. Helal. 1989. Some properties of microfine cement grouts. Civil Engineering Department, Northwestern University, Evanston, Illinois (unpublished).
- Lockwood Greene Engineers, Inc. 1988. Closure plan for Solid Waste Storage Area 6. Vol. 2: Interim corrective measures design. ORNL/RAP/Sub-87/99053/9&V2/R1. Oak Ridge National Laboratory.
- Luxmoore, R. J., B. P. Spalding, and I. L. Munro. 1981. Areal variation and chemical modification of weathered shale drainage characteristics. Soil Sci. Soc. Am. J. 45:687-691.
- SAS. 1985. SAS User's Guide: Statistics, Version 5 Edition. SAS Institute, Inc., Cary, North Carolina.
- Solomon, D. K., R. C. Haese, T. V. Dinsmore, and A. D. Kelmers. 1988. Sampling and analyses of SWSA 6 trench leachates and groundwaters. ORNL/TM-10813. Oak Ridge National Laboratory.

- Spalding, B. P. 1986. Burial trench dynamic compaction at a humid site. pp 676-689. In Proceedings of the Seventh Annual Participants' Information Meeting DOE Low-Level Waste Management Program. CONF-8509121. EG&G Idaho Falls, Idaho.
- Spalding, B. P. and T. A. Fontaine. 1992. Field demonstration of in situ grouting of radioactive solid waste burial trenches with polyacrylamide. pp. 415-425. In 2nd Volume. ASTM STP 1123, (Eds.) T. M. Gilliam and C. C. Wiles, American Society for Testing Materials, Philadelphia.
- Spalding, B. P., L. K. Hyder, and I. L. Munro. 1985. Grouting as a remedial technique for buried low-level radioactive wastes. *J. Environ. Qual.* 14(3):389-396.
- Spalding, B. P., G. K. Jacobs, and E. C. Davis. 1989. Demonstrations of technology for remediation and closure of Oak Ridge National Laboratory Waste Disposal Sites. ORNL/TM-11286. Oak Ridge National Laboratory.
- Spalding, B. P., S. Y. Lee, C. D. Farmer, L. K. Hyder, and P. Supaokit. 1987. In situ grouting of buried transuranic waste with polyacrylamide. pp. 39-76. In Oak Ridge Model Conference Proceedings. CONF-871075. Vol. 1, Pt 3. Martin Marietta Energy Systems, Inc., Oak Ridge, Tennessee.
- Tallent, O. K., E. W. McDaniel, R. D. Spence. 1987. Initial formulation results for in situ grouting of a waste trench at ORNL site No. 6. ORNL/TM-10299. Oak Ridge National Laboratory.
- Tamura, T., R. D. Spence, O. K. Tallent, and O. M. Sealand. 1987. In situ waste grouting of an ORNL trench using a particulate-type grout. ORNL/RAP-23. Oak Ridge National Laboratory.
- Zebovitz, S., R. J. Krizek, and D. K. Atmoatzidis. 1989. Injection of fine sands with very fine cement grout. *J. Geotech. Eng.* 115(12): 1717-1733.

APPENDICES

Appendix A

Soil Penetration Data after Grouting with Portland Type I Cement

Soil Depth (ft)	Location and Type of Test	Significance P < 0.05*	Blows per Foot				
			Ave.	Max	Min	%CV	N
1	Outside	B	5.1	8	2	26	51
	Pre-Grout	B	5.1	10	3	33	22
	Post-Grout	A	6.1	9	4	24	22
2	Outside	A	5.3	12	1	45	51
	Pre-Grout	A	5.3	9	4	21	22
	Post-Grout	A	6.4	9	4	21	22
3	Outside	A	10.0	37	2	69	51
	Pre-Grout	A	9.8	22	5	40	22
	Post-Grout	A	11.0	19	5	34	22
4	Outside	A	11.9	37	1	68	50
	Pre-Grout	A	11.0	22	6	39	22
	Post-Grout	A	12.7	40	6	60	22
5	Outside	A	19.7	100	1	85	50
	Pre-Grout	B	8.7	14	4	33	22
	Post-Grout	A	17.1	74	6	93	22
6	Outside	A	26.9	100	7	62	49
	Pre-Grout	B	10.8	53	4	91	22
	Post-Grout	AB	18.6	100	4	110	22
7	Outside	A	37.0	100	7	64	48
	Pre-Grout	C	8.8	14	4	34	22
	Post-Grout	B	20.4	90	4	109	21
8	Outside	A	38.2	100	10	56	43
	Pre-Grout	B	11.6	72	4	118	22
	Post-Grout	A	29.2	100	10	56	43
9	Outside	A	39.9	100	12	50	33
	Pre-Grout	B	11.7	25	1	49	21
	Post-Grout	A	39.7	100	4	95	18
10	Outside	A	39.9	100	12	50	33
	Pre-Grout	B	14.5	41	4	72	21
	Post-Grout	A	35.0	100	5	87	14

Appendix A

Soil Penetration Data after Grouting with Portland Type I Cement

Soil Depth (ft)	Location and Type of Test	Significance P < 0.05	Blows per Foot				
			Ave.	Max	Min	%CV	N
11	Outside	A	37.0	58	12	35	26
	Pre-Grout	B	14.8	72	4	101	21
	Post-Grout	A	43.7	100	13	65	13
12	Outside	A	46.2	100	10	50	23
	Pre-Grout	B	16.8	58	4	77	20
	Post-Grout	A	48.4	100	14	85	11
13	Outside	A	50.1	100	11	52	18
	Pre-Grout	B	23.6	100	5	97	17
	Post-Grout	AB	31.4	100	17	89	8
14	Outside	A	38.3	100	12	67	10
	Pre-Grout	B	21.9	49	7	65	14
	Post-Grout	A	46.3	78	21	48	7
15	Outside	B	35.7	68	15	49	7
	Pre-Grout	B	36.2	84	9	61	12
	Post-Grout	A	71.3	100	27	44	7

*For each soil depth, means with the same letter are not significantly different at P < 0.05.

Appendix B
Soil Penetration Data after Grouting with CMFC

Soil Depth (ft)	Location and Time of Test	Significance P < 0.05*	Blows per Foot				
			Ave.	Max	Min	%CV	N
1	Outside Trench	B	5.1	8	2	26	51
	After Portland Type I	B	6.1	9	4	24	22
	After CMFC	A	12.7	18	9	26	6
2	Outside Trench	B	5.3	12	1	45	51
	After Portland Type I	B	6.4	9	4	21	22
	After CMFC	A	13.2	20	9	28	6
3	Outside Trench	A	10.0	37	2	69	51
	After Portland Type I	A	11.0	19	5	34	22
	After CMFC	A	11.7	20	8	38	6
4	Outside Trench	A	11.9	37	1	68	50
	After Portland Type I	A	12.7	40	6	60	22
	After CMFC	A	11.3	19	6	50	6
5	Outside Trench	A	19.7	100	1	85	50
	After Portland Type I	A	17.1	74	6	93	22
	After CMFC	A	11.2	18	6	49	6
6	Outside Trench	A	26.9	100	7	62	49
	After Portland Type I	A	18.6	100	4	110	22
	After CMFC	A	13.5	41	5	101	6
7	Outside Trench	A	37.0	100	7	64	48
	After Portland Type I	AB	20.4	90	4	109	21
	After CMFC	B	12.0	27	4	80	6
8	Outside Trench	A	38.2	100	10	56	43
	After Portland Type I	A	29.2	100	10	56	43
	After CMFC	A	23.8	70	5	103	6
9	Outside Trench	A	39.9	100	12	50	33
	After Portland Type I	A	39.7	100	4	95	18
	After CMFC	A	55.7	100	8	73	6

Appendix B

Soil Penetration Data after Grouting with CMFC

Soil Depth (ft)	Location and Time of Test	Significance P < 0.05	Blows per Foot				
			Ave.	Max.	Min.	%CV	N
10	Outside Trench	A	39.9	100	12	50	33
	After Portland Type I	A	35.0	100	5	87	14
	After CMFC	A	20.8	28	10	37	4
11	Outside Trench	A	37.0	58	12	35	26
	After Portland Type I	A	43.7	100	13	65	13
	After CMFC	A	32.2	49	22	36	4
12	Outside Trench	A	46.2	100	10	50	23
	After Portland Type I	A	48.4	100	14	85	11
	After CMFC	A	28.5	42	20	34	4

*For each soil depth, means with the same letter are not significantly different at P < 0.05.

APPENDIX C

Soil Penetration Data from Trench 148

Soil Depth (ft)	Location and Type of Test	Significance P < 0.05*	Blows per Foot				
			Ave.	Max	Min	%CV	N
1	Outside Trench	B	5.1	8	2	25.8	51
	Pre-Grout	A	15.8	18	12	18.2	4
	Post-Grout	A	14.7	20	10	22.7	6
2	Outside Trench	B	5.3	12	1	45.2	51
	Pre-Grout	A	12.8	16	11	18.5	4
	Post-Grout	A	14.7	17	9	19.6	6
3	Outside Trench	A	10.0	37	2	69.1	51
	Pre-Grout	A	12.5	18	10	29.6	4
	Post-Grout	A	15.7	20	12	19.2	6
4	Outside Trench	A	11.9	37	1	67.8	50
	Pre-Grout	A	9.0	13	5	40.6	4
	Post-Grout	A	9.5	14	6	28.0	6
5	Outside Trench	A	19.7	100	1	85.1	50
	Pre-Grout	A	7.0	10	6	28.6	4
	Post-Grout	A	12.7	25	5	54.8	6
6	Outside Trench	A	26.9	100	7	61.7	49
	Pre-Grout	A	10.3	22	6	76.6	4
	Post-Grout	A	9.7	21	4	61.3	6
7	Outside Trench	A	37.0	100	7	64.3	48
	Pre-Grout	B	8.7	12	7	33.3	3
	Post-Grout	B	10.2	19	3	60.8	6
8	Outside Trench	A	38.2	100	10	55.9	43
	Pre-Grout	B	7.7	12	4	52.7	3
	Post-Grout	B	11.2	33	4	99.3	6
9	Outside Trench	A	40.5	100	9	46.4	39
	Pre-Grout	B	9.3	15	2	71.3	3
	Post-Grout	AB	22.0	80	5	148.0	5

APPENDIX C

Soil Penetration Data from Trench 148

Soil Depth (ft)	Location and Type of Test	Significance P < 0.05	Blows per Foot				
			Ave.	Max	Min	%CV	N
10	Outside Trench	A	39.9	100	12	50.3	33
	Pre-Grout	B	6.3	12	1	87.0	3
	Post-Grout	B	13.6	27	4	70.3	5
11	Outside Trench	A	37.0	58	12	35.0	26
	Pre-Grout	B	7.3	11	1	75.1	3
	Post-Grout	B	13.0	26	4	69.9	5
12	Outside Trench	A	46.2	100	10	50.0	23
	Pre-Grout	B	6.3	10	2	63.8	3
	Post-Grout	B	9.4	21	3	75.8	5

*For each soil depth, means with the same letter are not significantly different at P < 0.05.

INTERNAL DISTRIBUTION LIST

1. H. L. Adair
2. H. L. Boston
3. N. H. Cutshall
4. C. D. Farmer
5. C. J. Ford
- 6-12. C. W. Francis
13. S. B. Garland
14. D. D. Gates
15. D. F. Hall
16. S. G. Hildebrand
17. E. W. McDaniel
18. A. P. Malinauskas
19. C. A. Manrod
20. D. S. Marshall
21. B. C. McClland
22. L. E. McNeese
23. D. E. Reichle
24. T. F. Scanlan
- 25-30. B. P. Spalding
- 31-33. R. D. Spence
34. S. H. Stow
- 35-39. T. Tamura
40. J. R. Trabalka
41. S. D. Van Hoesen
42. Central Research Library
- 43-58. ESD Library
- 59-60. Laboratory Records Dept.
61. Laboratory Records, ORNL-RC
62. ORNL Patent Section
63. ORNL Y-12 Technical Library

EXTERNAL DISTRIBUTION

64. E. F. Barth, U.S. Environmental Protection Agency, 26 M. L. King Dr., Cincinnati, OH 45268
65. W. F. Bonner, Battelle Pacific Northwest Laboratories, P. O. Box 999, Richland, WA 99352
66. J. L. Buelt, Battelle Pacific Northwest Laboratories, P. O. Box 999, Richland WA 99352
67. E. Cox, Tennessee Department of Health and Environment, 701 Broadway, 4th Floor, Customs House, Nashville, TN 37219-5403
68. J. F. Franklin, Bloedel Professor of Ecosystem Analysis, College of Forest Resources, University of Washington, Anderson Hall AR-10, Seattle, WA 98195
69. Clayton Gist, U. S. Department of Energy, Oak Ridge Operations, P.O. Box 2001, Oak Ridge, TN 37831
70. R. C. Harriss, Institute for the Study of Earth, Oceans, and Space, Science and Engineering Research Building, University of New Hampshire, Durham, NH 03824

71. G. Y. Jordy, Director, Office of Program Analysis, Office of Energy Research, ER-30, G-226, U. S. Department of Energy, Washington, DC 20545
72. Emil Kowalski, Division Head, Repository Projects, NAGRA, Parkstrasse 23, CH-401, Baden, Switzerland
73. G. Loomis, EG&G Idaho, Inc., PO. Box 1625, Idaho Falls, ID 83415
74. Peter Manchak, P. O. Box 21708, Santa Barbara, CA 93121
75. R. H. Olsen, Professor, Microbiology and Immunology Department, University of Michigan, Medical Sciences II, #5605, 1301 East Catherine Street, Ann Arbor, MI 48109-0620
76. A. Patrinos, Director, Environmental Sciences Division, Office of Health and Environmental Research, ER-74, U.S. Department of Energy, Washington, DC 20585
77. T. J. Wheeler, U. S. Department of Energy, Oak Ridge Operations, P. O. Box 2001, Oak Ridge, TN 37831
78. F. J. Wobber, Environmental Sciences Division, Office of Health and Environmental Research, ER-74, U. S. Department of Energy, Washington, DC 20585
79. Office of Assistant Manager for Energy Research and Development, U. S. Department of Energy Oak Ridge Field Office, P. O. Box 2001, Oak Ridge, TN 37831-8600
- 80-89. Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge TN 37831.